FRACTURE TREAT

REPAIR WELL

SHOOT OR ACIDIZE

SHOOTING OR ACIDIZING

(Other) _

Form approved.

ABANDONMENT*

orm 9-331	į.	JN, _D STATES	SUBMIT IN TRIPLICE	
May 1963)	DEDARTM	IENT OF THE INT	FRIOR (Other instructions on re	5. LEASE DESIGNATION AND SERIAL NO.
				NM 14288-A
	G	EOLOGICAL SURVE	<u>r</u>	6. IF INDIAN, ALLOTTED OR TRIBE NAME
	CUNIDOM MOTE	CES AND REPORT	TS ON WELLS	G. IF INDIAN, ADDOTTED ON THE
	SUNDRY MOIT	CES AND REPORT	nlug back to a different revervoir	
(Do not t	use this form for propose 'Use "APPLICA	TION FOR PERMIT—" for s	plug back to a different reservoir. such proposals.)	
				7. UNIT AGREEMENT NAME
OIL U	GAS X OTHER		RECEIVED	
NAME OF OPE				8. FARM OR LEASE NAME
	st Oil Corporat	Federal "M "		
ADDRESS OF C		1011	— JUN 1 2 1973	9. WELL NO.
	Vilco Building	Midland	, Texas 79701	1 /
1 100 TON OF	wert (Report location cl	early and in accordance wit	h any State requirements.	10. FIELD AND POOL, OR WILDCAT
. LOCATION OF WELL (Report location clearly and in accordance with a See also space 17 below.) At surface			ARTESIA, DEFICE	Wildcat /
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
	2310' FNL &	72		
		-		Sec. 25, T22S R22E
14. PERMIT NO.		15. ELEVATIONS (Show wheth	ther DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
14. 156.111 1.01		Gr. 4350'		Eddy N. Mex.
			- Notes - Chlories Donor of	Other Data
16.	Check Ap	propriate box to indice	ate Nature of Notice, Report, or	the contract of the contract o
	NOTICE OF INTEN	TION TO:	SUBSE	EQUENT REPORT OF:
TEST WATER	SHUT-OFF I	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
1232 (7722)		WITTINIE COMPLETE	FRACTURE TREATMENT	ALTERING CASING

(Note: Report results of multiple completion on Weil Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

6-6-73 Ran 304 jts (9880') 42" 11.6# N-80 & K-55 csg, set @ 9879'. 1 guide shoe, 1 fill-up collar @ 9846, 5 cent., 8 scratch., 1 DV tool @ 8092 w/2 cmt baskets below. Cmt 1st stage: 100 sx Class "C" 50/50 3-poz, 2% D-20, .3 of 17% D-60, .2 of 1% D-65, 24/sk D-29, 350 sx Class "C" 1% D-60, .2 of 1% D-13, 2nd stage: Circ 6 hrs between stages. Pumped 380 sx Class "C" 50/50 poz, 4% D-20, 50 sx Class "C" 2% D-13. Plug dwn 4:01 AM 6-6-73.

> RECEIVED U. S. GEOLOGICAL SURVE ARTESIA, REM MEXIGO

18. Thereby cerulty that the foregoing is true and correct	TITLE Production Clerk	DATE 6-7-73
(This space for Federal or State office use) APPROVED BY CONDITIONS OF TERROVEL, IF ANY:	TITLE	DATE

*See Instructions on Reverse Side