, Rissa (1981)	N. 194. O. C.	C. COPY	1
Form 9-331 (May 1963)	UN ED STATES DEPARTMENT OF THE INTER	SUBMIT IN TRIP ATE: Other instructions 3, re-	Budget Bureau No. 42-R1424.
	GEOLOGICAL SURVEY	(IUR verse side)	5. LEASE DESIGNATION AND SERIAL NO.
	DRY NOTICES AND RED OR'S		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
JUNL (Do not use this f	or <u>for proposals to drill</u> or to deepen or plug	DR WELLS back to a different reserver. proposals.)	
1.	orm for proposals to drill or to deepen or plug Use "APPLICATION FOR PERMIT_" for such AUG 2 2 196	proposals.)	
OIL GAS WELL WELL		ECT. 1956	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR	OTHER OTHER OTHER O. C. C. ARTEBIA, DFFIC OFFI	RF 613 SUK	Big Eddy
PE1	RY R. BASS	AUC OGICALE MEXI	Big Eddy Unit
3. ADDRESS OF OPERATOR		S. GEULA NEW	9. WELL NO.
4. LOCATION OF WELL (Re	.78. Monahans, Texas	V. State requirements #	8
At surface 660 f	() Yom the north line and 10001	From the second 3 t	10. FIELD AND POOL, OR WILDCAT
of Sec. 30, To	Wnship 20 South, Range 31 F	Irom the West line	Big Eddy - Strawn 11. SEC., T., B., M., OE BLK. AND
New Mexico.	·	est, Eady County,	SURVEY OR AREA
14. PERMIT NO.			Sec. 30, T-20-S, R-31-E.
	15. BLEVATIONS (Show whether I		12. COUNTY OR PARISH 13. STATE
	3577 KDB. 3576 1		Eddy New Mexico
10.	Check Appropriate Box To Indicate	Nature of Notice, Report, or C	Other Data
NO	TICE OF INTENTION TO :	SOBSEC	JENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WOLL
FRACTURE TEDAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OB ACIDIZE Repair well	CHANGE PLANS	SHOOTING OR ACIDIZING (Other) Report of V	ABANDONMENT*
(Other)		(Unter) <u>Report results</u>	of multiple completion on Well etion Report and Log form.)
17. DESCRIBE PROPOSED OR C	COMPLETED OPERATIONS (Clearly state all pertine well is directionally drilled, give subsurface loc	ent details, and give pertinent dates,	including estimated date of starting any
rough a 3/8" cho rough a 3/8" cho l fluid going ou about 11,510. n-productive. O d Halliburton RT ing 200 sx. of T 480-11485, and 1 sx. in the form bing; ran bit; d 486-11492 with the me interval. Rai id over the perfect oke from 6000 ps; cuum 3 min. after pit. On 24 hr.	er, and 1411 MCF gas through est on 7-28-66 showed 274 bk ke. FTP 950 psi. A radioad t the bottom set of perforat The two top sets of perforat m 8-4-66, rigged up a pullin TS tool. Set a Halliburton rinity Inferno neat cement, 1489-11502 to a maximum press ation and 16 sx. in the casi rilled out to 11,500. Teste wo jet shots per foot. Unab n RTTS tool on 2-3/8" ODEUE orated zone; set the RTTS to i to 5400 psi. Finished tre r job completed. Job comple test ending 10:05 a.m. 8-13 4" choke. FTP 1750 psi. Ga	ols oil and 398 bbls. we tive tracer survey was tions (11489-11502), ar tions 11462-11467 and 1 ag unit, killed the wel drillable retainer at squeezed off the perfor sure of 6500 psi. Rev ng. Job completed 1:4 d casing to 4000 psi; le to break down with tubing; spotted 500 ga ol at 11,442. After a atment at 3 bbls. per ted at 5:00 a.m. 8-10- -66. flowed 427 bbls.	water in 24 hrs. flowing s run on 8-1-66, that showed ind then travelling downward 11480-11485 appeared to be 11 with brine, pulled tubing 11398-11400, on tubing. brated intervals 11462-11467 versed out 164 sx; left 45 a.m. 8-5-66. Pulled held. Pulled bit; perforate acid. Re-perforated the 1. Western "Intensified" woaking over night, formatio min. at 3200 psi. On
	<i>'</i>		
10 7 hand			
12-1	he foregoing is true and correct		
SIGNED Zala	Level Course TITLE AS	st. Div. Mgr.	DATE August 15, 1966
(This space for Federa			
APPROVED BY		PISTRICT ENGINEER	DATE
CONDITIONS OF APR	BOVAL, IF ANY:		
,			

ř

*See Instructions on Reverse Side

•

.