

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM 03677

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR <u>Harvey E. Yates</u>	8. FARM OR LEASE NAME <u>Stebbins Deep Fed.</u>
3. ADDRESS OF OPERATOR <u>305 Carper Bldg., Artesia, New Mexico</u>	9. WELL NO. <u>1</u>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <u>1980 fr N and 990 fr E, 30-20S-29E</u>	10. FIELD AND POOL, OR WILDCAT <u>Wildcat</u>
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <u>30-20S-29E</u>
15. ELEVATIONS (Show whether DE, RT, GR, etc.) <u>3236 GR</u>	12. COUNTY OR PARISH <u>Eddy</u>
	13. STATE <u>N.M.</u>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐

WELL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☐

(Other) Running of 7" casing.

X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We intend to run approx. 12,195' of 7" casing with float shoe and float collar on bottom joint with DV packer collar. Set @ 10,950. Also a D.V. multi. stage cementer @ 4500'

STAGE #1 - Cement thru shoe with 350 sks of type C with 8# of salt per sk.

STAGE #2 - (Via D.V. Packer Collar) Cement with 500 sks of trinity lite wate with 8# of salt per sk.

STAGE #3 - (Via D.V. Cementer @ 4500) Cement with 500 sks of 50-50 Pozmix A type C with 10# of salt per sk.

CONFIDENTIAL

NOT TO BE RELEASED

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Bookkeeper

DATE June 16, 1966

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE JUN 21 1966

CONDITIONS OF APPROVAL, IF ANY:

Oral Approval 6-18-66