

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. N.M. 03677
2. NAME OF OPERATOR Harvey E. Yates		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 112 North First, Artesia, New Mexico 88210		7. UNIT AGREEMENT NAME Harvey E. Yates
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <u>SW/4 SW/4 NE/4 2310' from North &amp; East Line of</u> <u>Sec. 30-T20S-R29E</u>		8. FARM OR LEASE NAME Stebbins Fed. <i>Deep</i>
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		10. FIELD AND POOL, OR WILDCAT <i>Wellcat</i> Sealion Delaware
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 30-20-29
		12. COUNTY OR PARISH Eddy
		13. STATE New Mex.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to Rig up Swabbing Unit and swab accumulated load water out of tubing in order to restore well to flowing status and run test on gas zone.

RECEIVED

OCT 16 1970

U. S. GEOLOGICAL SURVEY  
ARTESIA, N. M.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Paul White*

TITLE Engineer

DATE 10/14/70

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED

R. L. BEEKMA

ACTING

\*See Instructions on Reverse Side

RECEIVED

OCT 19 1970

D. C. C.  
ARTESIA OFFICE