

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

LC 070286

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hudson Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Golden Lane Strawn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 4, T-21-S, R-29-E

12. COUNTY OR PARISH

Eddy

13. STATE

N. M.

1. OIL WELL ☐ GAS WELL ☒ OTHER

APR 29 1977

2. NAME OF OPERATOR

Pennzoil Company D. C. C.

3. ADDRESS OF OPERATOR

ARTESIA, OFFICE

P. O. Drawer 1828 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

838, 1/4 FNL & 1650' FWL of Sec. 4, T-21-S, R-29-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3425' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

7-14-76 Rigged up casing pulling unit.

7-15-76 Pulled packer & tubing. Spotted 35 sx. cement plugs from 11,075' to 10,760'.

7-16-76 Tagged top of cement plug @ 10,760'. Circulate hole w/9.6+#/gal mud. Shot 5 1/2" casing off at 5463' (K3). Pulled & laid down 167 joints casing.

7-19-76 Set 50 sx. cement plug from 5493' to 5268'
Set 50 sx. cement plug from 4100' to 3916'
Set 350 sx. cement plug from 450' to 1515'

7-20-76 Tag cement @ 80'. Set 10 sx. cement plug in top of 8 5/8" casing.

Installed marker. P&A Complete.

Prep to back fill pits & level location.

RECEIVED

JUL 22 1976

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Advanced Petroleum Engineer DATE 7-21-76

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side