	-		
NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE /-			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE	—		State 📕 🛛 🛛 Fee
OPERATOR 3			5. State Oil & Gas Lease No.
· · · · · · · · · · · · · · · · · · ·			8-11555
SUND			
(DO NOT USE THIS FORM FOR P USE "APPLIC	DRY NOTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B ATION FOR PERMIT -" (FORM C-101) FOR SUC	ACK TO A DIFFERENT RESERVOIR. H PROPOSALS.)	
	7. Unit Agreement Name		
	Big Eddy Unit		
2. Name of Operator	8. Farm or Lease Name		
Perry R. Bass (Citia	s Service Oll Company - A	gent)	
3. Address of Operator	9. Well No.		
P. 0. Box 69, Hobbs	17		
4. Location of Well	10. Field and Pool, or Wildcat		
UNIT LETTER	Big Eddy Stram		
	560 FEET FROM THE NOT CH	LINE AND FEET F	
THE East LINE. SEC	TION 2 TOWNSHIP 215	29E	
THELINE, SEC	TION TOWNSHIP	RANGENM	PM- (()))))))))))))))))))))))))))))))))))
	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
$\sum_{i=1}^{n} \sum_{j=1}^{n} \sum_{i=1}^{n} \sum_{i$	3387 DF		Eddy
	Appropriate Box To Indicate N		
NOTICE OF	INTENTION TO:	SUBSEQUE	ENT REPORT OF:
			— –1
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	F1	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	
	_	OTHER Plug off	· · · · · · · · · · · · · · · · · · ·
OTHER		Form and	complete in Strawn
		<u> </u>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

T.D. 12913 Line P.B. 12533 Workover complete. Respud 1-29-68. Pulled tubing. Circulated hole w/salt water. Set packer @ 12550. Dumped 2 sacks cement on top of packer from 12550-12533. Ran 353 jts. of 2 $3/8^{11}$ 00 N-80 tubing set @ 11255 w/packer @ 11248. Perf. w/4 holes @ 11307. Swabbed dry. Attempted to acidize thru perfs. (11307) w/1000 gals. Formation would not breakdown @ 5800 PS1 on tubing and 2500 PS1 in annulus. Got communication to annulus. * Pulled tubing w/packer. Found bad collar and pin. Reren 2 $3/8^{11}$ 00 N-80 tubing set @ 11255 w/packer @ 11248. Reperf. w/4 holes @ 11307. Swabbed dry.e Attempted to re-acidize thru perfs. (11307) w/1000 gals. Formation to annulus. * Pulled tubing w/packer. Found bad collar and pin. Reren 2 $3/8^{11}$ 00 N-80 tubing set @ 11255 w/packer @ 11248. Reperf. w/4 holes @ 11307. Swabbed dry.e Attempted to re-acidize thru perfs. (11307) w/1000 gals. Formation would not breakdown @ 7500 PS1 on tubing and 3000 PS1 in annulus. Reversed out acid. Reacidized thru perfs. (11307) w/500 gals. breakdown acid and 500 gals. LST NE 15% Max. press. 5500 PS1, min. press. 1500 PS1. Treated @ 3/4 B/N @ 1500 PS1 1S1P 1200 PS1 5 min. S1P 1000 PS1 10 min. S1P 900 PS1. Swabbed and flowed load. Flowed on potential 86 80 + 350 BW/24 hrs. thru 14/64^u choke FTP 1600# GOR 7651 plus gas @ rate of 658 MCFPD. Recompleted 2-10-68.

* Reversed out acid.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

S { G N ED	ORIGETAL SIGNELS C. D. R.DSBELSON	TITLE	District Clerk	. DATE	February	12,	1968
APPROVED BY	W.a. Sugget-	TITLE	a 2 2 - Sector 2 - Sector 2 - Sector	DATE -	For the second sec		}

CONDITIONS OF APPROVAL, IF ANY: