


1-30-96 Requested permission to produce Strawn from present
zone with packer set at 10,135'. Verbally approved by
Mr. Shaw.  started testing tubing in hole w/packer.