

N. M. G. C. C. COPY  
UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRI  
(Other instruction  
verse side)ATE\*  
on reForm approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N.M. 0349881

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Miller Ranch Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Revelation Delaware

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 18, T-22S, R-25E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

NOV 15 1974

U. S. G. C.

ARTESIA, OFFICE

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Marathon Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 2409, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface1680' FSL & 1980' FEL, Section 18, Township 22-South,  
Range 25-East, Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

G.L. 3795'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Abandonment procedure was performed as follows:

1. Spotted 50-sack cement plug from 3680' back to 2800'.
2. Displaced hole with mud-laden brine.
3. Shot off 4 1/2" casing @ 1868' and pulled same out of hole.
4. Spotted 50-sack cement plug from 1918' back to 1250' with 25 sacks inside pipe and 25 sacks outside.
5. Spotted 20-sack cement plug in top of 8 5/8".
6. Cut off 8 5/8" three feet below surface, welded on plate and erected marker.
7. Removed all surface equipment from location.
8. Cleaned up location, including all pits and pulling unit tie

RECEIVED  
OCT 22 1974U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Operations Superintendent

DATE October 18, 1974

(This space for Federal or State office use)

APPROVED BY

DISTRICT ENGINEER

DATE

CONDITIONS OF APPROVAL, IF ANY: