Hanagan Po 1980 FNL Section 1	etroleum Corporation #1 State-Com & 1980' FEL 5-21S-25E
<u>Eddy Coun</u>	ty, New Mexico
4/28/69:	Spud @ 5:00 PM.
4/29/69:	Drlg. @ 105', lost circulation @ 87', dry drilled to 105'.
4/30/69:	TD 120', encountering difficulty in running conductor casing. Plan to drill 15-20' and run conductor.
5/1/69:	TD 140' WOC. Set 16" csg. @ 140' w/150 sx.
5/2/69:	Drlg. 332' w/air w/very little returns.
5/3/69:	Drlg. 532' w/no returns.
5/4/69:	Drlg. 790' w/no returns.
5/5/69:	Drlg. 905' w/no returns.
5/6/69:	Drlg. 1160' w/air, no returns. 13-3/4" hole reduced to 12-1/4" @ 1108'.

.

a e

RECEIVED

MAY 7 1969

D. C. C.

د. در در درو مریومی ورد در در