

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.  
*NA 0558961*  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

RECEIVED

7. UNIT AGREEMENT NAME  
*Springs Unit Com.*  
8. FARM OR LEASE NAME

2. NAME OF OPERATOR  
*Shenandoah Oil Corp.*

FEB 5 1975

3. ADDRESS OF OPERATOR  
*4805 Andrews Hwy. Midland, Texas*

9. WELL NO.  
*4*

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

O.C.C.  
ARTESIA, OFFICE

10. FIELD AND POOL, OR WILDCAT

*Upper Penn Gas*  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
*Sec 3, R21S, R25E NMPM*

*1000' f/NL 660 f/EL*

14. PERMIT NO.  
*Old Cities Service Lease*

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH  
*Eddy*  
13. STATE  
*N. Mex.*

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other)

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☐  
(Other)

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Set C. I. Bridge Plug @ 7991 with 35 ft. cement plug.
2. Shot casing off @ 4590 and pull casing
3. Circulate hole with 9.5# mud
4. Ran 35 sack cement plug @ 4700-4600
5. Ran 35 sack cement plug @ 2820-2720
6. Ran 10 sack cement plug @ 10-0
7. Install regulation dry hole marker.

RECEIVED  
MAY - 7 1974  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

RECEIVED  
MAY - 8 1974  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED *James E. Conner* TITLE *Dist. Prod. Supt.*

DATE *4-29-74*

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE