Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department		Form C-103 Revised 1-1-89	
DISTRICT 1 P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87509-2088-90		WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		Office	6. State Oil & Gas Lease No. K-675 & Fee	
SUNDRY NOTICES AND REPORTS ON WELLS ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well: OL OAS WELL OAS WELL X	OTHER		City of Carlsbad Com.	
2. Name of Operator Corinne	Grace		8. Well No.	
3. Address of Operator P.O. Box 1418, Carlsbad, NM 88220		9. Pool name or Wildcat S. Carlsbad Morrow		
4. Well Location Unit Letter <u>0</u> : <u>660</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line				
Section         25         Township         22S         Range         26E         NMPM         Eddy         County           10. Elevation (Show whether DF, RKB, RT, GR, etc.)         3226         DF         0 <td< td=""></td<>				
II.         Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data           NOTICE OF INTENTION TO:         SUBSEQUENT REPORT OF:				
	PLUG AND ABANDON	REMEDIAL WORK	X ALTERING CASING	
	CHANGE PLANS			
PULL OR ALTER CASING		CASING TEST AND CEMENT JOB		
OTHER:		OTHER:		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well loading severely, Acidized to prevent premature abandonment. Jet acidize with 500 gals 15% Mor-Flo BC and 10,000 SCF nitrogen at ½ bbl per minute and 200 SCF per minute rate. Flush with 250 gals treated water and nitrogen, Jet hole - Volume was 150 MCFD prior to treatment and 600 MCFD after treatment. Swabbed well to assist in recovering load. Slow, progress in recovering load with swabbing. Recovering load is also complicated by Transwestern high pipeline pressure in that well is unable to unload formation water, and loads at low producing rates.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SKINATURE Renture	mæ_Agent	DATE		
TYPEOR PRINT NAME JOE Huber		TELEPHONE NO.		
(This space for State Use)				
APPROVED BY MARCH Man	SUPERVISOR, DISTRICT II	FEB 1 3 1990		
CONDITIONS OF APPROVAL, IF ANY:				