

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

SEP 25 '90

WELL API NO.

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.  
K-675 & Fee

7. Lease Name or Unit Agreement Name

City of Carlsbad Com.

8. Well No.

1

9. Pool name or Wildcat

S. Carlsbad Morrow

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

Corinne Grace

3. Address of Operator

P.O. Box 1418, Carlsbad, NM 88220

4. Well Location

Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line

Section 25

Township 22S

Range 26E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3226 DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well loading severely, Acidized to prevent premature abandonment. Jet acidize with 500 gals 15% Mor-Flo BC and 10,000 SCF nitrogen at 1/4 bbl per minute and 200 SCF per minute rate. Flush with 250 gals treated water and nitrogen, Jet hole - Volume was 150 MCFD prior to treatment and 600 MCFD after treatment. Swabbed well to assist in recovering load. Slow progress in recovering load with swabbing. Recovering load is also complicated by Transwestern high pipeline pressure in that well is unable to unload formation water, and loads at low producing rates.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Joe Huber TITLE Agent

DATE 1-25-90

TYPE OR PRINT NAME Joe Huber

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

SEP 26 1990

CONDITIONS OF APPROVAL, IF ANY:

Corinne B. Grace

POST OFFICE BOX 1418  
CARLSBAD, NEW MEXICO 88220  
-----  
(505) 887-5581

RECEIVED

SEP 25 '90

C. D.  
ARTESIA, OFFICE

September 20, 1990

Mr. Mike Williams  
Oil Conservation Division  
P. O. Drawer DD  
Artesia, New Mexico 88210


Enclosed please find a sundry notice dated January 25, 1990, describing remedial work which was performed on the City of Carlsbad Well #1. Our records reflect the sundry notice was mailed but we believe it was inadvertently sent to the Santa Fe office of the Oil Conservation Division. Our review of the well file at the Santa Fe Office indicates the sundry notice could not be located in the well files. Evidently the Santa Fe office did not forward the notice back to your office. Nonetheless we wish to file this sundry notice out of time.

We apologize for any inconvenience this late filing may have caused.

As reflected by the well files we have had a hard time keeping this well flowing due to the well loading up. This same type of work had to be performed back in 1989.

Should you have any questions or if I can be of further assistance in this matter please let me know.

Very truly yours,

  
Suzette Johnson

Enclosure  
SLJ/sj