

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED  
NEW MEXICO OIL CONSERVATION COMMISSION

JUN 11 1971

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

O. C. C.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dry Hole</b>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <b>Cities Service Oil Company</b>		5. State Oil & Gas Lease No. <b>K-6460</b>
3. Address of Operator <b>Box 69 - Hobbs, New Mexico 88240</b>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <b>J</b> <b>1650</b> FEET FROM THE <b>South</b> LINE AND <b>1650</b> FEET FROM THE <b>East</b> LINE, SECTION <b>36</b> TOWNSHIP <b>22S</b> RANGE <b>24E</b> NMPM.		8. Farm or Lease Name <b>State CN Com.</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3914 DF</b>		9. Well No. <b>1</b>
		10. Field and Pool, or Wildcat <b>Rock Tank L. Morrow</b>
		12. County <b>Eddy</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**T.D. 10858 Shale. Plugged and abandoned. The above well was plugged and abandoned in the following manner:**

1. Loaded hole with mud laden fluid.
2. Displaced a 35 sack cement plug @ 10550-10450 (across the top of the Morrow)
3. Displaced a 50 sack cement plug @ 9812-9650 (across DST #2 interval)
4. Displaced a 35 sack cement plug @ 8600-8500 (across DST #1 interval)
5. Displaced a 35 sack cement plug @ 7600-7500 (across the top of the Dean)
6. Displaced a 35 sack cement plug @ 6500-6400.
7. Displaced a 35 sack cement plug @ 5000-4900.
8. Displaced a 35 sack cement plug @ 2850-2750 (across water zone @ 2796)
9. Displaced a 35 sack cement plug @ 2550-2450 ( $\frac{1}{2}$  in and  $\frac{1}{2}$  out of 8 5/8" casing set and cemented @ 2499 w/1080 sacks)
10. Displaced a 10 sack cement surface plug @ 30-0 w/a 4" dry hole marker extending 4' above ground to designate a plugged and abandoned location.
11. Location will be cleared of all equipment and debris and your office will be notified for final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED  
C. D. ROBERTSON

SIGNED \_\_\_\_\_ TITLE **District Admin. Supervisor**

DATE **5/18/71**

APPROVED BY *[Signature]*

TITLE **OIL AND GAS INSPECTOR**

DATE **12-6-71**

CONDITIONS OF APPROVAL, IF ANY: