

RECEIVED N. M. O. G. S.

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
**Federal NM-055473**

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

9. WELL NO.  
**Federal**

10. FIELD AND POOL, OR WILDCAT

11. SEC. T., R., M., OR BLK. AND  
SURVEY OR AREA  
**Wildcat**12. COUNTY OR PARISH 13. STATE  
**Sec. 11 T-21 R-24 E**  
**Eddy N. M.**

1.

OIL WELL ☐ GAS WELL ☐ OTHER ☒ **D & A**

2. NAME OF OPERATOR

**Titan Wells, Inc.**

3. ADDRESS OF OPERATOR

**P. O. Box 737 Marietta, Ohio 45750**4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface**800' F&L, 2460' F&L Sec. 11, T-21-S, R-24E**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**3556 GL**

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**September 11, 1971****Notified WGS office September 10, 1971 via telephone & received the following plugging procedure, plugged well accordingly.**

## Procedure:

1. Ran drill pipe open ended to 8214.
2. Halliburton Co. spotted cement plugs as follows:
 

|         |      |           |
|---------|------|-----------|
| Plug #1 | 25sx | 8214-8124 |
| #2      | 25sx | 6571-6471 |
| #3      | 25sx | 4897-4797 |
| #4      | 25sx | 3254-3154 |
| #5      | 10sx | surface   |

3. Removed well head & installed dry hole marker.
4. Broke out pits & leveled location.

RECEIVED

MAY 22 1972

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*William E. Anderson*TITLE **Consultant**DATE **2/7/72**


(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE



\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for special instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement plugs; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of packing of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking for approval of the abandonment.