

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP DATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER P&A		5. LEASE DESIGNATION AND SERIAL NO. NM 29201
2. NAME OF OPERATOR Yates Petroleum Corporation		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 800' FSL & 2460' FEL		8. FARM OR LEASE NAME Ambra AEK Federal
14. PERMIT NO. 20488 API #30-015-24088		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) C. D. 3654 3655' GR ARTESIA. OFFICE		10. FIELD AND POOL, OR WILDCAT Wildcat Yeso
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit 0, Sec. 11-T21S-R24E
		12. COUNTY OR PARISH Eddy
		13. STATE NM

RECEIVED BY
JAN 14 1987

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Propose to plug and abandon well as follows:

1. Spot cement plug thru tubing from 2350-2250'. Tag this plug.
2. Spot 100' plug at approximately 1300'.
Note: There is no salt section in this well.
3. Spot 100' plug inside 8-5/8" casing across 13-3/8" casing shoe at 348' from 400' to 300'.
4. Set 15 sack surface plug and install regulation abandonment marker.

Verbal approval to plug obtained from Mr. Armando Lopez, BLM, Roswell, NM, on 12-31-86 by Mr. Ray Stall.

18. I hereby certify that the foregoing is true and correct

SIGNED Ray Stall TITLE Production Supervisor DATE 12-31-86

(This space for Federal or State (not to be used) Signature)

APPROVED BY Armando Lopez TITLE Acting Area Manager DATE 1-12-87

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side