NO. OF COPIES RECEIVED	13	
DISTRIBUTION		
SANTA FE		
FILE	\square	
U.S.G.S.		
LAND OFFICE		
OPERATOR		}

DATE MAY 26 1972

NO. OF COPIES RECEI	AFD						VE			Form C-103
DISTRIBUTION	1						· L	- 0		Supersedes Old C-102 and C-103
SANTA FE		1		Ni	EW MEXIC	O OIL CON	ERVATION	COMMISSIO	N	Effective 1-1-65
FILE		ightharpoons				· 1	6 1972			
U.S.G.S.										5a. Indicate Type of Lease
LAND OFFICE						4	ينا. ليا.			State _y Fee
OPERATOR		1				ARTESI	A, DEFIGE			5, State Oil & Gas Lease No.
	_	1								L-1898
		SUI	NDR	Y NOTICES	AND RE	PORTS ON	WELLS			
(DO NOT USE T	HIS FOR	M FO	R PRO	Y NOTICES	L OR TO DEE	PEN OR PLUG	BACK TO A DIFF	ERENT RESERV	OIR.	
1.							,	·		7. Unit Agreement Name
OIL WELL	GAS Well	X		OTHER-						Catalaw Draw Unit
2. Name of Operator										Catclaw Draw Unit
Hanagar	n Pe	tro	ole	um Corp	oratio	n Ó				Catalaw Dnaw Unit
3. Address of Operator										Catclaw Draw Unit
P O F	3 n y	171	37.	Roswel	1. New	Mexic	88201			2
4. Location of Well	<u> </u>	1/,	,,,	NO SWC1	1 5 110 11	HCXIC	00201			10. Field and Pool, or Wildcat
	n			020		Nont	,	920		Catclaw Draw Morro
UNIT LETTER	<u>U</u>	•		920	T FROM THE	NOTE	LINE AND _	920	FEET FROM	Cacciaw Draw Morro
114				2.6		21.	•	255		
THE WEST	LI	ΝЕ, 5	ECT10	36	TOWNS	н1Р	RANGE	<u> </u>	НМРМ.	
kiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii	~~~	•	•							
		III	III	111111 15.			DF, RT, GR,	etc.)		12. County
	<u> </u>	\overline{m}	III		3400	GR, 34	SU NB			Eddy
16.	(Che	ck /	Appropriate	Box To	Indicate 1	Nature of N	otice. Rei	port or Otl	ner Data
٨				TENTION '			1	-	**	REPORT OF:
PERFORM REMEDIAL WO	ork 🗀				PLUG AND	ABANDON	REMEDIAL W	ORK		ALTERING CASING
TEMPORARILY ABANDON	\equiv						1	RILLING OPNS	Τ γ	<u> </u>
PULL OR ALTER CASING					CHANGE PL	ANG	l .	AND CEMENT		PLUG AND ABANDONMENT
'					CHANGE FE				ade [V]	
OTHER							OTHER			
		-				ـ				
17. Describe Proposed	or Con	plet	ed Op	erations (Clea	rly state all	l pertinent de	ails, and give	pertinent dat	es, including	estimated date of starting any proposed
work) SEE RULE	_	. اس	1			1.20 1	м /ма	nan Dwi	11100	Contractor)
5/10/72:										
5/12/12:										r casing (503') in
										light ¼# flocel 2%Ca
	+	50	SX	Class	ຼີ U" <i>*</i> 4#	FTIOCE	ı 2% tai	LI, CIN	· c . 100	sx excess, plug dow
	2:3	U	PM	(1.32 s)	lurry	VOI. C	u, ft./9	SX 85°	temp.	when slurry mixed
	est	•	fm.	temp.	75° co	mpress	ive str	ength 5	55 psi	12 hrs.).
5/13/72:	Dri	11	e d	plug 2:	30 AM	(WOC 1	2 hrs.)	Press	. up 6	00# 30 mins., no pre
	dro	р.		,						
5/15/72:	TD	21	30	- Ran 6	9 jts.	8-5/8	" new Al	PI 24#	ST&C s	urface casing (2152'
	wit	h	D۷	tool 0	969',	cmt. ls	t stage	300 sx	HOWCO	light 10# Gilsonite
	8#	Sa	1 t	1/4# fl	ocel 2	2% CaCl	+ 150	sx Clas	s "C" 1	/4# flocel 2% CaCl,
	ρĴu	α .	dow	n 3:00	PM. WC	C 4 hr	s cmt	. 2nd s	tage 3	00 sx HOWCO light 10
	Gil	50	nit	e 8# sa	1t 1/4	# floc	el 2% C	aCl. di	d not	circ., plug down 7:5
	PM.	Ī	et	set 6 h	rs. ra	n temp	. surve	v top c	ement	approx. 800'. Went i
	w/1	" _	t ha	6 773	cmt	25 sv	HUMCU	liaht 1	0# Gil	sonite 4% CaCl, set
	2 h	nc	T	'/cmt 75	6' cn	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	SY HOW	CO liab	+ 4% C	aCl w/l" @ 730', set
	h w c	1 3	 +	cmt 2	301 (ne. 100	SV HOW	CO ligh	+ 1% C	aCl, cmt. circ. @ 9:
		,	ray	1164 51	υσ 10·	.30 pm .111 c · /3	D M O C C	11 191	10 4 0 C	min., held.
	AM.		ו יז ט	ried pi	uy IU:	JU PM.	L1.622.	up 100	10π 30	min., neiu.
18. I hereby certify the	at the in	form	ation	above is true	and complet	e to the best	of my knowled	ge and belief	•	
. 1	^	_	. /	<u>^</u>						
Long will	///	マ タ	4,	and on			<u>Vice Pr</u>	asidant	-	DATE 5/25/72
SIGNED AND	10	• /	y U	~		TITLE	FICE FI	C3 I UEII (<u> </u>	DATE J/LJ//L

TITLE BIL AND GAS INSPECTOR