

| | |
|------------------------|---|
| NO. OF COPIES RECEIVED | - |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | ✓ |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

JAN 8 1976

| | |
|------------------------------|--|
| 5a. Indicate Type of Lease | State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> |
| 5. State Oil & Gas Lease No. | L-1898 |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|--|-----------------|--|
| 1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Plug & Abandon | ARTESIA, OFFICE | 7. Unit Agreement Name Catclaw Draw Unit |
| 2. Name of Operator Hanagan Petroleum Corporation | | 8. Farm or Lease Name Catclaw Draw Unit |
| 3. Address of Operator P. O. Box 1737 Roswell, New Mexico 88201 | | 9. Well No. 3 |
| 4. Location of Well UNIT LETTER D, 920 FEET FROM THE North LINE AND 920 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 21S RANGE 25E NMPM. | | 10. Field and Pool, or Wildcat Catclaw Draw Morrow&Strawn |
| 15. Elevation (Show whether DF, RT, GR, etc.) 3480 KB | | 12. County Eddy |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

| | | | |
|--|--|---|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plan to plug & abandon subject well as discussed by phone with Mr. Gressett. Orig. T.D. 10,930, present P.B.T.D. 10,410' (Morrow perms. sqzd. off), present perms. (4 holes) in Strawn 9546-56, top cmt. by temp. survey 9000'. Plan to salvage as much 5½" csg. as possible above 9000', will fill csg. with heavy drilling mud plus uncased part of hole, 8-5/8" csg. set @ 2130' w/7-7/8" hole to total depth. Set plugs as follows (35 sx.): 50' in & out stub of 5½" csg., 8000-8100, 6250-6350, 4340-4440 & in & out 8-5/8" csg. 2080-2180, 10 sx. plug @ surface w/appropriate dry hole marker. Work to be performed next week.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

| | | |
|-----------------------------------|--------------------------------------|-------------------------|
| SIGNED <u>Hugh E. Hanagan</u> | TITLE <u>Vice President</u> | DATE <u>1/7/76</u> |
| APPROVED BY <u>W. A. Gressett</u> | TITLE <u>SUPERVISOR, DISTRICT II</u> | DATE <u>JAN 13 1976</u> |

CONDITIONS OF APPROVAL, IF ANY:

Notify N.M.O.C.C. in sufficient time to witness.

Plugging after 5½" csg. recovered