	erty (C. 1		TILLINT OF T EAU OF LAND N				LEASE DESIGNATI	UN AND SEEI	IAL Set
	SUN		DTICES AND		N WELLS	6	IF INDIAN, ALLOT	THE OR TRIB	E DAMI
				a		r.			
] .				UEC 9	10 31 AN RECEIVE	D 7.	UNIT AGREEMENT	NAME	
OIU WEI		X OTHER		CARL					
	IE OF OPERATOR			AREA ISES	EUEC 29 '8	37 ^{8.}	FARM OR LEASE		
	CO INC. V RESS OF OPERATOR						E. J. Leve	rs Fede	ral
PO B	ox 728, Hob	bs, New	Mexico 882	40	O. C. D		1		
See	ATION OF WELL (Re also space 17 belo surface	port locatio w.)	n clearly and in acco	ordance with any S	State require ARTESIA, OFF		Catclaw Dr		т
		660 T M T	s 1980 FW	Soction 12	, T21S, R25E	11	Morrow Gas		
UNIL	Letter N,	000 FML	a 1960 rwh,	Section 12	, 1215, RZJE		SURVEY OR AS		
14. PER	NIM NO			Chart shathan PR			<u>Sec. 12, T</u>		
14. I BK	MIL MU,		i .	(Show whether DF,	RT, GR, etc.)	12	COUNTY OR PARI		
16.		<u> </u>	3338'		····		Eddy	NM	
10.				to Indicate No	ature of Notice, Repo	rt, or Othe	r Data		
	N	OTICE OF INT	TENTION TO :	ŋ		SUBSEQUENT	REPORT OF :	_	
	ST WATER SHUT-OF	F	PULL OR ALTER CA		WATER SHUT-OFF		REPAIRING	G WELL	_
	OOT OR ACIDIZE		MULTIPLE COMPLE ABANDON®	TE	FRACTUBE TREATME!		ALTERING		
	PAIR WELL		CHANGE PLANS		(Other) Perf a	addition	ABANDONN al pav	i]
	ther)	t	CANUE IDAN		NUTE Report	t results of r	nultiple completion Report and Log	n on Wall	X
1)	-	-	t. Killed w	ell. Insta	lled hydraulic	BOP and	choke mani	fold.	POH
1) 2)	with tubi	ng.			lled hydraulic with 35' cemen			fold.	POH
·	with tubi Set 4 1/2 TIH with	ng. " CIBP tubing	at 10250'. and spotted	Capped CIBP 200 gallons	with 35' cemen acetic acid fr	t. New om 10208	PBTD: 102	15'.	
2) 3)	with tubi Set 4 1/2 TIH with inhibited	ng. " CIBP tubing 2% KCL	at 10250'. and spotted . TOH. Tes	Capped CIBP 200 gallons ted 4 1/2"	with 35' cemen acetic acid fr casing to 4000	t. New om 10208 psi. He	PBTD: 102 8' to 10078 21d OK.	15'. '. Cir	cula
2)	with tubi Set 4 1/2 TIH with inhibited Ran in ho	ng. " CIBP tubing 2% KCL le with	at 10250'. and spotted . TOH. Tes 2 3/8" tubi	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack	t. New om 10208 psi. He er with	PBTD: 102 3' to 10078 21d OK. wireline r	15'. '. Cir e-enter	cula Y
2) 3)	with tubi Set 4 1/2 TIH with inhibited Ran in ho	ng. " CIBP tubing 2% KCL le with on/off	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/	with 35' cemen acetic acid fr casing to 4000	t. New om 10208 psi. He er with	PBTD: 102 3' to 10078 21d OK. wireline r	15'. '. Cir e-enter	cula Y
2) 3)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back	ng. " CIBP tubing 2% KCL le with on/off 10050' side to	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi.	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500	t. New om 10208 psi. He er with g tested 0'. Wer	PBTD: 102 3' to 10078 eld OK. wireline r 1 to 7000 p at in hole	15'. '. Cir e-enter si. Se with l	cula Y t 9/16
2) 3) 4) 5)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175'	t. New om 10208 psi. He er with g tested 0'. Wer to 10180	PBTD: 102 3' to 10078 eld OK. wireline r 1 to 7000 p nt in hole 0' (6 feet,	15'. '. Cir e-enter si. Se with l 24 hol	cula Y t 9/16
2) 3) 4)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'-	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo	PBTD: 102 ' to 10078 d OK. wireline r to 7000 p t in hole ' (6 feet, prrow-Flo A	15'. '. Cir e-enter si. Se with 1 24 hol cid.	cula Y t 9/16 es).
2) 3) 4) 5)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'-	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175'	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo	PBTD: 102 ' to 10078 d OK. wireline r to 7000 p t in hole ' (6 feet, prrow-Flo A	15'. '. Cir e-enter si. Se with 1 24 hol cid.	cula Y t 9/16 es).
2) 3) 4) 5)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi.	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mc IP: 2100	PBTD: 102 d to 10078 d OK. wireline r to 7000 p t in hole (6 feet, prrow-Flo A) psi; 15 M	15'. '. Cir e-enter si. Se with 1 24 hol cid. in. SIP	cula Y t 9/16 es).
2) 3) 4) 5)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi.	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1	PBTD: 102 d to 10078 d OK. wireline r to 7000 p t in hole (6 feet, prrow-Flo A) psi; 15 M	15'. '. Cir e-enter si. Se with 1 24 hol cid. in. SIP hour.	cula y t 9/16 es). :
2) 3) 4) 5)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi.	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1	PBTD: 102 ' to 10078 ' d OK. wireline r t to 7000 p t in hole ' (6 feet, prrow-Flo A) psi; 15 M .ine in one	15'. '. Cir e-enter si. Se with 1 24 hol cid. in. SIP hour.	cula y t 9/16 es). :
2) 3) 4) 5)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi.	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1	PBTD: 102 ' to 10078 eld OK. wireline r l to 7000 p ot in hole (6 feet, prrow-Flo A psi; 15 M ine in one CEPTED FO	15'. '. Cir e-enter si. Se with 1 24 hol cid. in. SIP hour. R RECC	cula y t 9/16 es). :
2) 3) 4) 5)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi.	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1	PBTD: 102 ' to 10078 ' d OK. wireline r t to 7000 p t in hole ' (6 feet, prrow-Flo A) psi; 15 M .ine in one	15'. '. Cir e-enter si. Se with 1 24 hol cid. in. SIP hour. R RECC	cula y t 9/16 es). :
2) 3) 4) 5) 6) 7)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi. On Octobe	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940 r 21, 1	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre 987, the wel	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A 1 produced	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1 AC	PBTD: 102 ' to 10078 eld OK. wireline r l to 7000 p ot in hole (6 feet, prrow-Flo A psi; 15 M ine in one CEPTED FO	15'. '. Cir e-enter si. Se with 1 24 hold cid. in. SIP hour. R RECC } 1987	cula y t 9/16 es). :
2) 3) 4) 5) 6) 7)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi. On Octobe	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940 r 21, 1	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A 1 produced	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1 AC	PBTD: 102 1 to 10078 1 d OK. wireline r 1 to 7000 p 1 to 7000 p	15'. '. Cir e-enter si. Se with 1 24 holo cid. in. SIP hour. R RECO } 1987 EW MEX	cula y t 9/16 es). :
2) 3) 4) 5) 6) 7)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi. On Octobe	ng. " CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940 r 21, 1	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate cions 10175'- psi; AVG pre 987, the wel	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A 1 produced	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS 31 MCF into the	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1 AC	PBTD: 102 1 to 10078 1 d OK. wireline r 1 to 7000 p 1 to 7000 p	15'. '. Cir e-enter si. Se with 1 24 holo cid. in. SIP hour. R RECO } 1987 EW MEX	cula y t es). :
2) 3) 4) 5) 6) 7)	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi. On Octobe	ng. "CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940 r 21, 1 n 21, 1	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate tions 10175'- psi; AVG pre 987, the wel	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A 1 produced	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS 31 MCF into the	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1 AC	PBTD: 102 1 to 10078 1 d OK. wireline r 1 to 7000 p 1 to 7000 p	15'. '. Cir e-enter si. Se with 1 24 holo cid. in. SIP hour. R RECO } 1987 EW MEX	cula y t 9/16 es). :
2) 3) 4) 5) 6) 7) 8. I her sign (Thi	with tubi Set 4 1/2 TIH with inhibited Ran in ho guide and packer at Load back perforati Acidized Max. pres 1170 psi. On Octobe	ng. "CIBP tubing 2% KCL le with on/off 10050' side to ng guns perforat : 2940 r 21, 1 n 21, 1	at 10250'. and spotted . TOH. Tes 2 3/8" tubi tool with Z 1000 psi. . Perforate tions 10175'- psi; AVG pre 987, the wel	Capped CIBP 200 gallons ted 4 1/2" ng and 4 1/ N profile (Swabbed flu d with 4 JS 10180' with s: 2500'; A 1 produced	with 35' cemen acetic acid fr casing to 4000 2" Otis PL Pack 1.875"). Tubin id level to 500 PF from 10175' 1500 gallons 7 IR: 2.6 EPM; IS 31 MCF into the	t. New om 10208 psi. He er with g tested 0'. Wen to 10180 1/2% Mo IP: 2100 sales 1 AC	PBTD: 102 1 to 10078 1 d OK. wireline r 1 to 7000 p 1 to 7000 p	15'. '. Cir e-enter si. Se with 1 24 holo cid. in. SIP hour. R RECO } 1987 EW MEX	cula y t 9/16 es). :

*See Instructions on Reverse Side