

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP
(Other instruction
reverse side)

Budget Bureau No. 1004-
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

INDREX, Inc. ✓

3. ADDRESS OF OPERATOR

7633 E. 63rd Place, Suite 500, Tulsa, Oklahoma 74133

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface

1980' ENL & 660' FEL

Ut. H

14. PERMIT NO.

NM-65387

15. ELEVATIONS (Show whether OF, AT, OR, OR)

3471 Gr

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Four Forks Federal

9. WELL NO.

1

10. FIELD NO. FOR WILDCAT
Hoped Mesa BS
Wildcat

11. SEC. T., R., S. OR S.E. AND
SURVEY OR AREA

Sec 15, T-22-S, R-25-E.

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETION

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT

REPAIR WELL

CHANGE PLANT

(Other)

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and codes
pertinent to this work.)

The captioned well is to be abandoned as uneconomical.

Post IO-2
2-26-93
P+H

1. Pull production equipment.
2. Set CIBP @ 4300' & cap w/35' cement.
3. Free point, cut and lay down 5-1/12" casing from 1200'.
4. RIH w/2-3/8" cbg & displace hole w/9.5 ppg mud laden fluid.
5. Spot 100' cement plug @ 2225'.
6. Spot 100' cement plug @ csg stub.
7. Spot 100' cement plug @ 540'.
8. Spot 50' cement plug @ surf.
9. Cut off heads. Clean location.



18. I hereby certify that the foregoing is true and correct

SIGNED

Mickey Dolan

TITLE Agent for INDREX, Inc.

DATE 5-28-89

(This space for Federal or State agency use)

APPROVED BY

David A. Glass

TITLE

DATE 12/30/92

CONDITIONS OF APPROVAL IF ANY: