

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED
CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501
AUG 20 87

O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
2. Name of Operator TXO Production Corp.	5. State Oil & Gas Lease No.
3. Address of Operator 900 Wilco Bldg. Midland, Tx 79701	7. Unit Agreement Name
4. Location of Well UNIT LETTER 0 1980 FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 13 TOWNSHIP 22-S RANGE 26-E NMPM.	8. Farm or Lease Name City of Carlsbad
15. Elevation (Show whether DF, RT, GR, etc.) 3149' GR 3162' KR	9. Well No. 1
	10. Field and Pool, or Wildcat South Carlsbad Dele
	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-18-87 MI & RU PU
7-20-87 POH w/tbg & pkr
7-21-87 Set CIBP @ 11,290' w/35' cmt
7-22-87 Spot 25 sx CL "H" @ 10,002', spot 25 sx CL "H" @ 10,150', spot 35 sx CL "H" @ 8526'. Set CIBP @ 8035' w/35' cmt.
7-23-87 Perf 5121-27, 5135-37, 5150-55 w/25 SPF
7-24-87 Acidized from 5121-5155 w/1400 gals 15% NEFE. Swb dwn
7-27-87 Set CIBP @ 5110' w/35' cmt. PBDT 5075'. Perf 4595-4611' w/2 SPF Total 34 holes.
7-29-87 Acidized from 4595-4611 w/500 gals 15% NEFE
8-1-87 Squeezed 4595-4611 w/485 SX Trinity Lite & 100 sx CL "C" neat.
8-4-87 Drld retainer & cmt to PBDT of 5075'. Reperf 4595-4611 w/2 SPF. Total 34 holes
8-5-87 Spot 250 gals 15% NEFE
8-6-87 Acidized w/1600 gals 15% NEFE.

Post ID-2
8-21-87
P4A M.M.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Tim Houdreau TITLE Production Engineer DATE 8/17/87

Original Signed By

Las A. Houdreau

Supervisor District II

TITLE _____ DATE AUG 26 1987

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY: