Form 9-331	UNITED ST	TATES	SUBMIT IN	TRIPLICATE	Tudao	approved. et Bureau No. 4
(May 1963)	DEPARTMENT OF T	THE INTERIO	(C.1.)	ructions on re	5. LEASE DESIG	NATION AND SE
	GEOLOGICAL			.	- NM 01 $$ 6. IF INDIAN, A	
SUN	DRY NOTICES AND	REPORTS O	N WELLS		* *	
(Do not use this	s form for proposals to drill or to Use "APPLICATION FOR PER	o deepen or plug ba MIT—" for such pro				
1. OIL CAS			RECE		7. UNIT AGREEN	NEAT NAME
WELL WELL 2. NAME OF OPERATOR	OTHER	/	FEB	5 1975	8. FARM OR LE	
	um Corporation		red		Superior	<u>r-Federa</u>
3. ADDRESS OF OPERATO	alara Dallas Tox	vag 75219	0.0	C. C.	2	
4. LOCATION OF WELL (See also space 17 be	Report location clearly and in acc	cordance with any S	State requirements	GFFICE	10. FIELD AND	
At surface	/				Wildcat	M., OR BLK. AN
ITM: + D 6601	ENI and 1000' EE	т			SUBVEY	OB AREA
	FNL and 1980' FE		bm ap -4-1		Sec. 1,	T20S, R
14. PERMIT NO.	15. ELEVATIONS	s (Show whether DF, 3325	RT, GR, EUC.)		Eddy	N.
10	Check Appropriate Box		atura al Nati	Ranat at		
16.	Check Appropriate Boy NOTICE OF INTENTION TO:	x to indicate No	arure or inotice		QUENT BEPORT OF:	
			WATER SHO	Г		AIRING WELL
TEST WATER SHUT- Fracture treat	OFF PULL OR ALTER C MULTIPLE COMPL		FRACTURE 1	1-		ERING CASING
SHOOT OR ACIDIZE	ABANDON*		SHOOTING O	OR ACIDIZING	ABA	NDONMENT*
REPAIR WELL	CHANGE PLANS		(Other)			nletion on We
			(NOTI	: Report resul	ts of multiple com	Log form)
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1	973. ran 2 3/8" tub	bing to 1642	t details, and give ions and measured feet and d	isplaced	piction Report and re, including estim- ical depths for all 430 sx Cla	ated date of st markers and z
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	if well is directionally drilled, gr)*	ing to 1642	t details, and give ions and measured feet and d	isplaced	piction Report and re, including estim- ical depths for all 430 sx Cla	ated date of st markers and z
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured feet and d	isplaced	piction Report and re, including estim- ical depths for all 430 sx Cla	ated date of st markers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured feet and d	isplaced	piction Report and re, including estim- ical depths for all 430 sx Cla	ated date of st markers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured feet and d	isplaced	piction Report and re, including estim- ical depths for all 430 sx Cla	ated date of st markers and z
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured feet and d	isplaced	piction Report and re, including estim- ical depths for all 430 sx Cla	ated date of st markers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured feet and d	isplaced	piction Report and re, including estim- ical depths for all 430 sx Cla	ated date of st markers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured ions and measured feet and d and cut off	letion or Recomposition pertinent date and true vert isplaced 8 5/8" ca	430 sx Cla asing, welc	ated date of st markers and z
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured ions and measured feet and d and cut off	RECE	430 sx Cla asing, welc	ated date of st markers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured ions and measured feet and d and cut off	RECE	430 sx Cla asing, welc	ated date of simarkers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	t details, and give ions and measured ions and measured feet and d and cut off	RECE MAR 14	430 sx Cla asing, welc 10/50/50 430 sx Cla asing, welc 430 sx Cla 430 sx Cla	ated date of simarkers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	ing to 1642	L Comp t details, and give ions and measured feet and di and cut off	RECE MAR 14 S. GEOLOX	430 sx Cla asing, welc IVED 1973	ated date of simarkers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3 installed 4 inc	973, ran 2 3/8" tub 00 feet. Set 10 sx i h marker. P&A on	ing to 1642 in surface a 3/7/73.	L Comp t details, and give ions and measured feet and di and cut off	RECE MAR 14	430 sx Cla asing, welc IVED 1973	ated date of st markers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3 installed 4 inc	973, ran 2 $3/8$ " tub 00 feet. Set 10 sx i	oing to 1642 in surface a 3/7/73.	L Comp t details, and give ions and measured feet and di and cut off	RECE MAR 14 S. GEOLOXI	430 sx Cla asing, welc is including estim- training, welc asing, welc 11/ED 1973 AL SURVEY MEXICO	ated date of st markers and s
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3 installed 4 inc 18. I hereby certify th SIGNED	973, ran 2 3/8" tub 00 feet. Set 10 sx i h marker. P&A on	oing to 1642 in surface a 3/7/73.	L Comp t details, and give ions and measured feet and d and cut off U.	RECE MAR 14 S. GEOLOXI	430 sx Cla asing, welc asing, welc 11VED 1973 AL SURVEY MEXICO	ated date of stimarkers and a standard d
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3 installed 4 inc 18. I bereby certify th SIGNED (This space for Fe	973, ran 2 3/8" tub 00 feet. Set 10 sx i h marker. P&A on at the foregoing is true and corr	oing to 1642 in surface a 3/7/73.	L Comp t details, and give ions and measured feet and d and cut off U.	RECE MAR 14 S. GEOLOXI	430 sx Cla asing, welc asing, welc 1973 1973 AL SURVEY MEXICO	ated date of st markers and z ded plate
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3 installed 4 inc 18. I bereby certify the SIGNED (This space for Ferrice) APPROVED BY	973, ran 2 3/8" tub 00 feet. Set 10 sx i h marker. P&A on at the foregoing is true and corr	oing to 1642 in surface a 3/7/73.	L Comp t details, and give ions and measured feet and d and cut off U.	RECE MAR 14 S. GEOLOXI	430 sx Cla asing, welc 19/5 D 1973 Al SURVEY MEXICO	ated date of st markers and 2 ss "C" c ded plate
(Other) 17. DESCRIBE PROPOSED proposed work. nent to this work. On March 6, 1 from 1642 to 3 installed 4 inc 18. I bereby certify the SIGNED (This space for Fernille)	973, ran 2 3/8" tub 00 feet. Set 10 sx i h marker. P&A on at the foregoing is true and corr	oing to 1642 in surface a 3/7/73.	L Comp t details, and give ions and measured feet and d and cut off U.	RECE MAR 14 S. GEOLOXI	430 sx Cla asing, welc asing, welc 1973 1973 AL SURVEY MEXICO	ated date of st markers and 2 ss "C" c ded plate