

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TR  
(Other instructi  
verse side)DATE  
on reForm approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 0331649A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "L"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Carlsbad South

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

34-22S-26E

12. COUNTY OR PARISH 13. STATE

Eddy

New Mexico

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

Midwest Oil Corporation ✓

3. ADDRESS OF OPERATOR

1500 Wilco Building Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

1980' FSL &amp; 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

Gr. 3310.5

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

12-8-73 WH press 1120#. Op bradenhead to blow dwn.

12-11-73 WH press 0.

12-12-73 Blowing small amt of gas &amp; small slugs of condensate. Pump 470 bbls 10% brine wtr dwn csg. Well unbalanced. BC &amp; gas out bradenhead. Pick up on csg; csg appears to be hanging free.

12-13-73 Pull out of hole w/241 jts 4½" csg.

12-14-73 Pulled remainder 4½" csg; total 315 jts (10,206'). Some btm jts were bent &amp; corkscrewed. Pump 50 bbls brine wtr dwn csg. (Total load 520 bbls) LD 74 jts csg standing in derrick. Moved in 2 7/8" DP for work string.

12-16-73 Ran in hole w/fishing tools &amp; caught 2" tbg @ 10,177'. Jarred on fish 1 hr &amp; pulled free. Pulled out of hole w/wet drl string, fishing tools &amp; LD cut off jt tbg, 8' collapsed jt of csg &amp; 10' collapsed jt of tbg. Left well open over nite.

12-18-73 Moved in mud pump, truck, drlg mud, &amp; wash over equip. Prep to mud up hole.

18. I hereby certify that the foregoing is true and correct

SIGNED

Bonnie Husband

TITLE

Production Clerk

DATE

12-19-73

(This space for Federal or State office use)

APPROVED BY

J. L. Kraft

TITLE

DISTRICT ENGINEER

DATE

DEC 20 1973

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side