ENERGY AND MINERALS DEPARTMENT		
CONSERVATION DIVISION		
DISTRIBUTION P. O. BOX 2088	Form C-103 - Revised 10-1-78	
SANTA FE SANTA FE, NEW MEXICO 87501	La Indunta Turned Law	
LAND OFFICE ANG 12'88	Sa. Indicate Type of Leuse State Fee X	
OPERATOR	5. State Oil & Gas Lease No.	
O, C. D.		
SUNDRY NOTICES AND REPORTS ON WELES & THIS FORM FOR PROPOSALS		
	7. Unit Agreement Name	
2, Name of Operator	B. Form or Lease Name	
Pennzoil Company	Moore Com.	
P.O. Drawer 1828, Midland, TX 79702-1828	9. Well No.	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER I 2310 FEET FROM THE South LINE AND 660 FEET FROM	Carlsbad Wolfcamp, S.	
THE East LINE, SECTION 23 TOWNSHIP 22-S RANGE 26-E MMPM.		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
<u>3178' G.L.</u>	Eddy	
Check Appropriate Box To Indicate Nature of Notice, Report or Oth	ber Data	
NOTICE OF INTENTION TO: SUBSEQUENT	REPORT OF:	
PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING	
"EMPORARILY ABANDON	PLUG AND ABANDONMENT	
PULL OR ALTER CABING . CHANGE PLANE . CASING TEST AND CEMENT JOB		
OTHER		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed	
work) SEE RULE 1903.		
It is proposed to permanently abandon the subject well as follows:		
Plug #1 Set C.I.B.P. @ 9550' with 35' of cement		
Plug #2 100' (25 sacks) from 8770-8670'.		
Plug #3 100' (25 sacks) from 8380-8280'. Plug #4 50' in & out of 5 172" stub @ + 6000'. 50 sacks. Tag cmt.		
Plug #5 100' (50 sacks) 5457-5357'. Tag cement.		
Plug #6 50' in & out of 9 5/8" stub @ + 2000'. 100 sacks. Tag cmt.		
Plug #7 100' (100 sacks) from 425-325'. Plug #8 10' surface with marker.		
-	Tops	
Delawa Bone S		
ABO	8330'	
Wolfca		
<u>.</u>		
Diagrams showing existing wellbore and proposed plugging are attache	ed.	
13. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
early Kand M Hoom Title Engineer	BATE 8-11-88	
Original Signed By	AUG 2 3 1988	
APPROVED BY	. DATE	
	14	
\Box t	<i></i>	
Plugging	* \	
i i		

∇	t	•
٢	lugg	10-