

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. NAME OF OPERATOR Manzano Oil Corporation 505/623-1996	3. ADDRESS OF OPERATOR P.O. Box 2107/Roswell, NM 88202-2107	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FNL & 1650' FEL Sec 8 21S 27E	5. LEASE DESIGNATION AND SERIAL NO. NM-56530	6. INDIAN, ALLOTTEE OR TRIBE NAME	7. UNIT AGREEMENT NAME	8. FARM OR LEASE NAME Radke Federal	9. WELL NO. 1	10. FIELD AND POOL, OR WILDCAT Cedar Hills-Bone Spring	11. SEC., T., R., M., OR BLK. AND SUBST OR ASSA Sec 8 T21S R27E	12. COUNTY OR PARISH Eddy	13. STATE NM
14. PERMIT NO. 30-015-20877	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3275' GR		16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data									

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)

PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)

REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

10/25/88 MIRU POH set CIBP @ 7200' Dump 35' of cement on top set CIBP @ 6400'
10/26/88 Spot 5 sacks @ 6400' circulate hole w/mud.
10/27/88 Shoot casing @ 3977' & lay down
10/28/88 Mix 35 sacks of Class "C" 4030 WOC tag plug @ 3774 POH 2600' Spot 55 sacks
10/29/88 Tag plug @ 2480, mix 45 sacks 608 to 472. Mix 10 sacks @ surface cut WH off & install DHM. Rig down.

Post ID-2
2-3-89
P+H

18. I hereby certify that the foregoing is true and correct

SIGNED Jackie Midkiff TITLE Jackie Midkiff/Landwoman DATE 1/16/89
(This space for Federal or State office use)
APPROVED BY WILLIAM J. MURPHY TITLE WILLIAM J. MURPHY DATE 1-27-89
CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well
Liability under bond is retained until
surface restoration is completed

*See Instructions on Reverse Side