

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

MAY 14 1991

O. C. D.

| |
|---|
| WELL API NO. 30-015-20892 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. K-3402 |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER | 7. Lease Name or Unit Agreement Name Stonewall DD Com |
| 2. Name of Operator YATES PETROLEUM CORPORATION ✓ | 8. Well No. 1 |
| 3. Address of Operator 105 South 4th St., Artesia, NM 88210 | 9. Pool name or Wildcat Undes. Burton Flat Wolfcamp |
| 4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 20 Township 20S Range 28E NMPM Eddy County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3250' GR | |

| | |
|---|--|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data | |
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| | OTHER: Set CIBP's, perforate, treat Wolfcamp <input checked="" type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-11-91. Tested perforations 10266-10320'. Straddled perms 10266' to 10320'. Pumped into Strawn zone at 2½ BPM @ 4500#. Started to swab. Recovered 68 bbls water. Used 80 bbls 2% water during test. Swabbed dry.

4-17-91. Set CIBP at 10390' and capped w/35' Class H cement to abandon Atoka. Set CIBP at 10060' and cap w/35' Class H cement to abandon Strawn. Perforated Wolfcamp 9508-9520' and 9097-9101' w/36 - .41" holes (2 SPF). Acidized perms 9508-9520' w/2500g. 15% NEFE acid. Acidized perms 9097-9101' w/1000g. 15% NEFE acid. Acidized original perms 8917-8954' w/2500g. 15% NEFE acid + ball sealers. Straddled all Wolfcamp perms 8917-9520' and started to swab.

Well returned to production 4-26-91 producing from Wolfcamp perforations 8917-8954', 9097-9101' and 9508-9520'

Note: Well completed in Wolfcamp perforations 8917-8954' in May, 1974.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 5-13-91

TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY

TITLE

DATE

MAY 16 1991

CONDITIONS OF APPROVAL, IF ANY: