

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

JAN 25 1994

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

30-015-20892

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South Fourth Street - Artesia, NM 88210

4. Well Location

Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line

Section 20

Township 20S

Range 28E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3250' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Perforations & acid ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-18-93 - Moved in and rigged up pulling unit. Nippled down wellhead. Strip on BOP. Released packer & TOOH. WIH w/4" casing gun and perforated 5718-5876' w/15 .42" holes as follows: 5718-5726' w/5 holes and 5823-5876' w/10 holes. TIH w/packer and RBP. Straddled perforations 5823-5876'. Break at 2700#. Opened by-pass. Spot acid to packer. Acidized perforations 5823-5876' w/1500 gallons 7-1/2% NEFE acid with ball sealers. Moved tool and straddled perforations 5718-5726'. Break at 2600#. Spot acid to packer. Acidized perforations 5718-5726' with 500 gallons 7-1/2% NEFE acid with ball sealers. Moved tool and straddled all perforations 5718-5876'. Swabbing.
12-19-20-93 - Swabbing.
12-21-93 - Swabbed. Released packer and RBP. TOOH. Removed tool. TIH open ended to 6200'. Strip off BOP. Flanged up wellhead. Shut in.
12-22-31-93 - Shut in.
1-1-21-94 - Shut in.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Rusty Klein

TITLE

Production Clerk

DATE January 21, 1994

TYPE OR PRINT NAME

Rusty Klein

505-748-1471
TELEPHONE NO.

(This space for State Use)

SUPERVISOR DISTRICT II

JAN 27 1994

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: