

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
LAND OFFICE	1
U.S.G.S.	1 ✓
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

FEB 7 1975

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K 5090
7. Unit Agreement Name K
8. Farm or Lease Name JCW State Com.
9. Well No. 2
10. Field and Pool, or Wildcat Winchester-Morrow
12. County

SUNDRY NOTICES AND REPORTS ON WELLS **O. C. C.**
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) **ODessa, OFFICE**

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-
2. Name of Operator Hillin Production Company
3. Address of Operator Box 152 - Odessa, Texas 79760
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE West LINE AND 1980 FEET FROM THE South LINE, SECTION 2 TOWNSHIP 20S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER Temporarily abandon <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Produce "Morrow" zone, 11,215' to 11,225' using compressor. Production not adequate to feed compressor. Rig up pulling unit, trip tubing, go in hole open ended & spot 100 sx. class "H" cement over perf's. & 100 sx. from 9000' to 10,000'. W.O.C. test casing to 4,000# - drill out cement to 9350' - Perf. "Wolfcamp" 9150, 52, 54, 56, 58, 60, 62, 64 & 92, 96, 98, 9200 (12 holes) & acidize w/3000 gal. acid. Swab & Test well. No commercial production. Shut well in & remove all surface equipment from location. Temporarily abandon well. Will plug & abandon well when plugging equipment is available.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *B. H. Hillin* TITLE Owner / Operator DATE 1-09-75

APPROVED BY *W. R. Gussett* TITLE SUPERVISOR, DISTRICT II DATE FEB 7 1975

CONDITIONS OF APPROVAL, IF ANY: Submit C-103 Notice of Intent to P & A for approval prior to commencing work