

JM State Com 1  
Cedar Hills

5-10-74. Ran 170 jts 2 3/8" 4.7# 8rd EUE "short string" tbg in hole changing regular collars to turned down collars. SD for nite.

JM State Com 1  
Cedar Hills

5-11-74. Finished in hole changing out collars. Tally showed 8' off. Appeared to sting in pkr. Went in w/plug - Attempted to pressure up to set pkr. Circulated to annulus. Pulled blanking plug. Re-ran blanking plug - circ. Ran another plug - no success. SD for nite.

5-12-74. Removed well head - picked up on 2 3/8" & worked down 6'. Assembled well head. Replaced seal. Packed off. Ran plug - pressured up & set pkr. Pressured up on annulus to 500 psi for 30 min. Held OK. Equalized & pulled blanking plug in 2 7/8" - Had 300' fluid in 2 7/8" tbg. when equalized. Got slight blow when equalized. Dropped bar - no indication that guns fired. Continued to get very slight blow for 2 1/2 hrs. SI.

5-13-74. SI 12 hrs. SITP 100 psi., FL 700' in hole - (400' increase). Went in w/slick line. Picked up bar. Jarred on firing head. No change. Prep to cut off guns & perf w/thru tbg gun.

JM State Com 1  
Cedar Hills

5-13-74. Cut off perf guns @ 11,351'. Could not get deep enough w/thru tbg gun to perforate. Prep to pull tbg strings & pkrs, fish guns & re-run.

JM State Com 1  
Cedar Hills

5-14-74. Disconnected well head. Installed BOP. Pulled short string 2 3/8". Changed rams in BOP. Loaded 2 7/8" tbg w/10# brine. Unseated pkrs. Well kicked off - sttd flowing. Killed w/10# brine. Pulled 80 stds. Kicked off. Killed w/10# brine. Pulled up to dual pkr. Closed BOP. SD for nite.

5-15-74. Small blow on tbg & csg. Bled off. Pulled out of hole. Prep to fish tbg conveyed guns.

JM State Com 1  
Cedar Hills

Finished out of hole. Laid down dual hydraulic pkr & Uni Pkr VI. Picked up bumper sub & 2 3/8" overshot w/ cutrite controller. Tagged fish at 11,526'. Worked on fish 1 hr. Came out of hole w/out fish. Prep to run center spear this a.m.

JM State Com 1  
Cedar Hills

Fishing for Vann perforating gun assembly in 4 1/2" liner. Ran center spear on tbg - did not recover fish. Leroy thinks fish was caught but was dropped while coming out of hole. Dressed spear & sttd in hole - ran almost to fish. SI for nite. This a.m. prep to try to set spear and pull fish.

Fish in hole:

Top 27' of 2 3/8" EUE 8rd N80 tbg - top has been cut w/jet tbg cutter 4' below top of jt.

1 jt 31.78' of 2 3/8" EUE 8rd N80 tbg.

1 tbg sug 6.13' 2 3/8" EUE 8rd N80.

1 - 3 1/8" OD firing head 1.60'.

41.13' of 3 1/8" OD steel cased jet guns.

Total of fish: 107.64'.

Fishing inside 4 1/2" 11.6# N80 Liner (ID=4.000").

JM State Com 1  
Cedar Hills

Set O'Bannon center spear into fish and pulled out of hole. Marks on spear indicated that spear had caught fish - but had not held. Ran impression block via wire line - impression indicated that tubing not split. Sttd in hole w/HE Center Spear w/spring loaded slips to try to pull fish. Lacked 40 jts being on bottom. Had to SI for nite due to high pressure. This a.m. prep to continue fishing w/HE Spear.