


Lavers Federal #2 SWD
1650' FSL & 1650' FEL, Sec. 2-T21S-R25E
Eddy County, New Mexico

Procedure to Test Well for Casing Integrity

1. Contact BLM in Carlsbad at 505-887-6544 48 hours before beginning procedure.
2. RU pump truck with pressure chart on 5-1/2" casing valve of well.
3. Pressure up on casing/tubing annulus to 550 psi. Hold for 30 minutes while recording on chart. Maximum allowable pressure bleed off is 10%.
4. After 30 minutes bleed off pressure and send chart to Midland office.


Doug Keathley
Northern Regional Engineer