

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI-STATE
(Other instruction
reverse side)

Form approved.
Budget Bureau No. 1004-1
Expires August 31, 1985

45F

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

2. NAME OF OPERATOR

TXO Production Corp.

3. ADDRESS OF OPERATOR

415 W. Wall Suite 900, Midland, TX. 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

1980' FNL & 660' FWL

SEP 13 '89

C. D.
ARTESIA, OFFICE

5. LEASE DESIGNATION AND SERIAL

NM 01165

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Yates Federal

9. WELL NO.

3

10. FIELD AND POOL OR WILDCAT

Wildcat (Delaware)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

17-20S-29E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3280' GL

12. COUNTY OR PARISH

Eddy

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANE

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

(7-27-89) MI RU PU. Kill Well w/40 bbls 2% KCL wtr. POH w/tbg & pkr.
set CIBP @ 10,300' w/35' cmt.

(7-28-89) tc
Ran temp-noise logs.

(7-30-89)

(7-30-89) SI F/Sunday

(7-31-89) Pump 435 bbls 10# brine dwn 4 1/2 csg. w/full returns.

(8-1-89) Pump 180 bbls 11.2# mud. Lost circ. Pump 225 bbls 16# mud w/80% returns.
POH w/109 jts 4 1/2" csg. TIH w/tbg. Tag csg stub @ 4463'. Set sx plug @ 4538'. WOC 2 hrs. Tag cmt. @ 4472'.

(8-2-89) Spot 40 sx plug @ 4473'. WOC 2 1/2 hrs. Tag cmt @ 4363'.

(8-3-89)

to Mill on junk. Recover 10 jts. 4 1/2 csg.

(8-8-89)

(8-9-89) Run 4 1/2", 10.5#, K55STC csg. Set @ 4170. Cmt. w/500 gals mud flush
and 450 sx "C".

(8-10-89) Ran Temp svy. TOC @ 2400'.

(8-11-89)

to WOC

(8-13-89)

(Continued)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineer

DATE

8/18/89

(This space for Federal or State office use)

APPROVED BY

(ORIG. SGD.) DAVID R. GLASS

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side