

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED
MAR 07 1983
O. C. D.

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL <input type="checkbox"/> GAS <input checked="" type="checkbox"/> WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator C & K PETROLEUM, INC. 3. Address of Operator P. O. Drawer 3546, Midland, Texas 79702 4. Location of Well UNIT LETTER 0, 660' FEET FROM THE South LINE AND 1980' FEET FROM THE East LINE, SECTION 14 TOWNSHIP 22S RANGE 26E NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) 3188' 41"	7. Unit Agreement Name 8. Farm or Lease Name Harold Olive Com. 9. Well No. #1 10. Field and Pool, or Wildcat Stallard Well 12. County Eddy
---	--

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug #1: Set 7" CIBP @ 10,050'. Cmt w/35 sx to 9950'.
Plug #2: 9900' - 9800' w/35 sx cmt.
Plug #3: 8775' - 8675' w/35 sx cmt. Stuck tbg @ 7813'. Shot tbg off @ 7805'. Left 8' tbg stub & CIBP setting tools in hole @ 7805' - 7813'. Tagged.
Plug #4: 6847' - 6747' w/35 sx cmt. Free point 7" csg @ 1500'. Shot 7" csg @ 5138', unable to move, shot 4710', csg free. Pull csg. Cmt. 50' in/out & tagged.
Plug #5: 5171' - 5071' w/35 sx cmt.
Plug #6: 4675' - 4543' w/35 sx cmt, tagged. Cut off 9-5/8" @ 1,116'. Pulled 9-5/8" csg.
Plug #7: 2307' - 2207' w/35 sx cmt.
Plug #8: 1162' - 1054' w/50 sx cmt. Tagged.
Plug #9: 246' - 50' w/35 sx cmt. Circ cmt to surf. Cut off 13-3/8" csg flange, weld cap on stub, installed dry hole marker.
P&A 3-02-83

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Carol DeGroot

TITLE Sec. to Operations Mgr.

DATE 3-04-83

APPROVED BY Nancy Brooks

TITLE Geologist

DATE 7-27-84

CONDITIONS OF APPROVAL, IF ANY: