

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0558282

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lowe-Federal

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

Golden Lane

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 31, T20S, R30E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

APR 28 1977

2. NAME OF OPERATOR

3. ADDRESS OF OPERATOR

Suite 300, 3535 N.W. 58th St., Oklahoma City, Okla. 73112

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 760' FEL of Section, Elevation 3306.64 GL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3306.64' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) **Change zones**

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Ran TDTlog 11,045-12,200' 5-21-76.
2. Set CIBP 11,160', driftable pkr. @ 11,075'. Pumped 75 ex. CIs. "H" w/6% Hallad 9 @ 2000#, 3 BPM. Squeezed 11,105-11,110' w/final press. 4500#. Pumped in 35 ex., rev. out 40. Final press. 4500#. Job complete 6:00 P.M. 5-22-76.
3. Tagged top of cmt. 11,073' & drld. pkr., cmt., & washed to 11,150' 5-23-76.
4. Prep. to finish POOH 5-24-76.
5. Finished POOH, RU Schl. & perf. 11,104-108' w/4 SPF. Ran 5-1/2" Mod. "R" dbl. grip pkr. & 352 jts. 2-3/8" thg. Pkr. set @ 11,040.88' w/13,000#. Tested csg. to 1000#. RU tree, swabbed 5-25-76.
6. Swabbed 5-26 & 5-27-76. Rec. acid & SW, very little gas. Well SI for further evaluation or P & A.

RECEIVED

APR 27 1977

**U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE **Manager of Drilg. & Prod. Oper.** DATE **4-25-77**

(This space for Federal or State office use)

APPROVED BY

TITLE **ACTING DISTRICT ENGINEER**

DATE **APR 27 1977**

CONDITIONS OF APPROVAL, IF ANY:

UNLESS FURTHER APPROVED, WELL MUST
BE PUT TO BENEFICIAL USE OR PLUGGED BY
APRIL OCTOBER

OCT 17-1977

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

Y400

1701 82 0 10

10 11 12
10 11 12 13 14 15