

SEP 29 1981

O. C. D.

ARTESIA OFFICE

NO. OF COPIES	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-4278
7. Unit Agreement Name --
8. Name of Lease Name Heyco State
9. Well No. 1
10. Field and Pool, or Wildcat Golden Lane (Strawn)
12. County Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☐ GAS WELL ☒ OTHER ☐

Name of Operator
Equina Oil Corporation

Address of Operator
P. O. Drawer 2960, Midland, Texas 79702

Location of Well
UNIT LETTER E, 1980 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 32 TOWNSHIP 20S RANGE 30E N.M.P.M.

15. Elevation (Show whether DF, RT, GR, etc.)

3322' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

FORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

OTHER ☐

PLUG AND ABANDON ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

COMMENCE DRILLING OPS. ☐

CASING TEST AND CEMENT JOBS ☐

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has watered out and no further remedial work or recompletion attempts are contemplated. It is proposed that the 8-5/8" and 4-1/2" casing strings be pulled at their free-points and cement plugs be placed in the well at the following depths.

Plug #	No. Sacks	
1	CIBP w/50'	10,800' (Perfs 10,873-939')
2	50'	Across 4-1/2" casing stub
3	50'	Across any 7-7/8" open hole interval in excess of 1500'
4	75	Across 8-5/8" casing stub
5	75	Across 8-5/8" casing shoe
6	75	Across any 11" open hole interval in excess of 1500'
7	75	Across 11-3/4" casing shoe
8	25	Surface

The plugs will be spotted thru open ended tubing and the wellbore between plugs will be loaded with mud type fluid. See attached wellbore diagram. The wellhead will be cut off and a dry hole marker installed. Notice will be given so that all plugs may be witnessed if desired.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ron Silbreach TITLE Production Manager DATE September 22, 1981

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: