C COPIES RECEIVED TRIBUTION	4		NEW MEXICO OIL CONSERVATION COMMISSION	Form C -103 Supersedes Old C-102 and C-103 Effective 1-1-65		
U.S.G.S.	+			5a. Indicate Type of Lease		
LAND OFFICE			JUN 2 8 1974	State Fee X		
OPERATOR	1	-	JUN 2 0 13/4	5. State Oil & Gas Lease No.		
(DO NOT USE THIS P	SU		Y NOTICES AND REPORTS ON WELLS U. C. C. POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DAMRINESTARSENTING CE ION FOR PERMIT			
1.				7. Unit Agreement Name		
OIL X GAS			OTHER-	8. Farm of Lease Name		
2. Name of Operator						
Cities Service	Simpson A Com.					
3. Address of Operator	9. Well No.					
Box 1919 - M	1					
4. Location of Well				10. Field and Pool, or Wildcat		
UNIT LETTERH			1980 FEET FROM THE LINE AND BLO FEET FROM	Wildcat Wolfcamp		
	LINE,	SECTIO	29 21S 27E NMPM			
		\square	15. Elevation (Show whether DF, RT, GR, etc.) 3154' GR.	12. County Eddy		
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						
PERFORM REMEDIAL WORK			PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING		
PULL OR ALTER CASING			CHANGE PLANS CASING TEST AND CEMENT JOB COMPLETION D	ata X		
OTHER						

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

T.D. 11,801' Shale. PBTD 10,000' waiting on pipeline connection. C0 to 10,000 & spotted 250 gals. 10% Acetic Acid @ 9915-9665'. Ran cement bond log. Top of cement @ 9446'. Cement bond good 10,000-9910' with slight channel 9910'-9446'. Tested 5-1/2" casing to 1500# - Held OK. Perforated for block squeeze with 4-0.41" holes @ 9031'. Ran tubing with cement retainer @ 9018'. Squeezed thru perfs @ 9031' with 100 sacks Class H with 0.6% Halad 9 + 50 sx Class H Neat 145 sacks in formation, 1-1/2 sacks in casing and reversed out 3-1/2 sacks. Max press 3000# - Held OK. Pulled tubing. Perforated with 4-0.41" holes @ 9002'. Ran tubing with RTTS set @ 8800. Press Annulus to 1500# - Held OK. Press.Wolfcamp perfs @ 9002' to 1600# for 5 mins. Held OK. Increased press to 3600#. Bled off to 2800# in 10 and to 2300# in 20 mins. Perfs too tight to squeeze. Pulled tubing and RTTS. Drilled retainer @ 9018' and cement to 9022' and washed down to 9048'. Tested casing and squeeze job to 1500# for 30 min. Held OK. Washed down to PBTD 10,000'. Spotted 250 gals. 10% Acetic Acid 9900'-9650'. Set a Baker Model DB Packer & 9650' (Bottom of tubing seal assembly @ 9689'). Perforated the Canyon Zone with 2-0.25" holes each @ 9794', 9796', 9798', 9800', 9802', 9804', 9806' and 9808'. Swabbed part of load and swabbed dry. 16 hr SITP 600#. Acidized thru Canyon perfs 9794'-9808' with 3600 gals. DS-30 15% Acid with 124,000 SCF Nitrogen + 24 Ball Sealers. Max. press. 7050# (Balled out), min press. 5950#, formation broke @ 5950#. AIR 8.5 B/M @ 6800#.

18. I hereby certify that the information above is true and comple	te to the best of my knowledge and belief.	
SIGNED Expenden	Region Oper. Mgr.	DATE June 26, 1974
APPROVED BY W. a. Gressett	OIL AND GAS INSPECTOR	JUL 9 1974

CONDITIONS OF APPROVAL, IF ANY: