

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYCOPY
SUBMIT IN TRI
(Other instruction
reverse side)

ATE*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

FED 0915

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR		8. FARM OR LEASE NAME
PERRY R. BASS		BIG EDDY UNIT
3. ADDRESS OF OPERATOR		9. WELL NO.
Box 2760, MIDLAND, TEXAS 79701		40
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface		10. FIELD AND POOL, OR WILDCAT
1980' FNL + 1980' FEL OF SECTION - UNIT LETTER G.		WILDCAT
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH
		13. STATE
		EDDY N. MEX

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SET CEMENT RETAINER AT 12,627'. SPOTTED 40 SKS
CLASS C CEMENT ON TOP. SPOTTED 1,100 GALS 10% ACETIC ACID AT
12,100'. SET PACKER AT 11,294'. PERFORATED ATOKA FROM 11,894-
11,908', 12,020'-12,036', + 12,044'-12,049' w/2 JSPF. ONE (1)
SHOT AT 12,047' AND ONE (1) SHOT AT 12,049' FAILED. PULLED
OUT AND RESET PACKER AT 11,306'. ACIDIZED WITH 5,000 GALS
7 1/2% HCl WITH N₂. ACIDIZED WITH 3,000 GALS 20% HCl AND
FORTY (40) BANN SEALERS.

RECEIVED

JUN 3 1976

JUN - 1 1976

O. C. C.
ARTEBIA, OFFICEU. S. GEOLOGICAL SURVEY
ARTEBIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

H. A. Wooten, Jr.

TITLE Division Production Chemist

DATE May 23, 1976

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.