

PERRY R. BASS

Box 2760

MIDLAND, TEXAS 79701

June 1, 1976

New Mexico Oil Conservation Commission
Drawer DD
Artesia, New Mexico 88210

Attn: Mr. W. A. Gressett

Re: Big Eddy Unit No. 40,
G, 22, 21S, 29E, Eddy
County, New Mexico

Gentlemen:

We request exception from the provisions of Rule 1122 on the above well.


The very low gas rate coming up 2½" tubing causes significant heading problems even at 400 MCFD and 20 BWPD. A four point test with rates of 200 MCFD would head even worse and result in very erroneous calculated surface pressures. Also a 338 hour pressure buildup test did not reach stabilization and was building at 5 psi/24 hrs. It is seriously doubted that any normal flow rate times would result in stabilized flow rates.

If you do not agree and desire that we run a four point test please call Mr. Alan Roberts at 915-684-5723.

Very truly yours,


J. E. Pullig
Division Manager

CAR/dh


Approved
6-6-76
W.A.G.

RECEIVED

JUN 4 1976

O. C. C.
ARTESIA, OFFICE