TRIBUTION	5		RECEIVED	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
FILE	1	4	JUN 1 1 1971	5a. Indicate Type of Lease
LAND OFFICE	1			State X Fee
OPERATOR	13		0.0 0.	5, State Oil & Gas Lease No.
l	<u></u>		ARTESIA, DEFL.S	L-1618
(DO NOT USE THIS F				
1. OIL GAS WELL WEL	_ X]	OTHER-	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name			
Cities Service (State CP Com.			
3. Address of Operator	9. Well No.			
Box 1919 - Midla	1			
4. Location of Well				10. Field and Pool, or Wildcat
		1	830 FEET FROM THE South LINE AND 1980 FEET FROM	Undes. Burton Flat Mor.
			ON 9 TOWNSHIP 21S RANGE 27E NMPM.	///////////////////////////////////////
	12. County Edd y			
16. NOT			Appropriate Box To Indicate Nature of Notice, Report or Oth NTENTION TO: SUBSEQUENT	her Data r REPORT OF:
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [PLUG AND ABANDON REMEDIAL WORK COMMENCE DRILLING OPNS.	ALTERING CASING
OTHER				actions ad data of starting any proposed

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

T.D. 2985' Lime & Sand. Prep to drill ahead. Drilled to a T.D. of 2980' and ran 13 Jts. (558.431) 9 5/8" OD 40# N-80 and 54 1/2 Jts. (2401.751) 9 5/8" OD 32.3# H-40 casing set and cemented @ 2980' w/825 sacks Halliburton Lite w/1/2# Flocele and 5# Gilsonite/sack, 2% CaCl2 followed by 300 sacks Class C w/2% CaCl2 cement. Shut down pumps approx. 10 minutes to move in hopper w/Class C cement. Resumed pumping cement but did not regain circulation. Fumped 300 sacks Class C plus 20 B. Wtr. behind wiper plug. Pressure increased to 2350#. Could not move pipe. Cement locked up. Found top of cement inside 9 5/8" OD csg. @ 297 . DO cement to 2480' and ran cement bond log. Top of cement @ 1840'. Ran 1" tubing in annulus to 1054'. Could not get deeper. Mixed and pumped 50 sacks Class C w/4% CaCl2 cement. WOC 2 Hrs. Filled up 91' (1054'-963'). Mixed and pumped 100 sacks Class C w/4% CaCl2cement. WOC 2 Hrs. Filled up 496' (963'-467'). Mixed and pumped 100 sacks Class C w/2% CaCl, cement. Cement circulated. Circulated 20 sacks to pits. WOC 21 Hrs. Total WOC time of 25 Hrs. Tested 9 5/8" OD casing to 1500# for 30 minutes with no drop in pressure. Drilled cement and 1/2 shoe jt. Tested to 1500# - Held O.K. Drilled rest of shoe jt. and 5' of formation to 2985'. Pressure tested w/Halliburton to 350# @ 1/2 B/M rate for 15 minutes -Held - O.K. (eq. mud wt. 10.5#/Gal.).

Leland Mermis w/NMOCC witnessed cementing job.....

		est of my knowledge and belief.	
alened Equilibri	TITLE _	Region Operation Manager	DATE JUNE 11, 197)
APPROVED BY	TITLE_	OIL AND GAS INSPECTOR	DATE JUN 2 5 1974