

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-0554235

6. IF APPLICABLE, LOT OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL ☐ GAS ☒ OTHER ☐

DEC 02 '88

Nov 10 12 11 PM '88

2. NAME OF OPERATOR

Pennzoil Company

O. C. D.
ARTESIA OFFICE

8. FARM OR LEASE NAME
Penn-Federal

3. ADDRESS OF OPERATOR

P. O. Drawer 1828 - Midland, Texas 79702-1828

9. WELL NO.

1

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

10. FIELD AND POOL OR WILDCAT
Golden Lane (Morrow)

1980' FNL & 1980' FWL of Section 31, T-20-S, R-30-E

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Section 31, T-20-S,
R-30-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3307.6 GR

12. COUNTY OR PARISH

Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

Spotted cement plugs as follows:

09/29/88: Plug #1, 100 sx Class "H" from 8200' to 11746'

10/02/88: Plug #2, 145 sx Class "C" from 7350' to 7923' TAGGED

10/04/88: Plug #3, 35 sx Class "C" from 3975' to 4116' TAGGED SJS

10/05/88: Plug #4, 40 sx Class "C" from 1550' to 1650'
Plug #5, 110 sx Class "C" from 200' to 500'
Plug #6, 20 sx Class "C" from surface to 60'
Plug #7, 15 sx Class "C" down 8-5/8" casing.

10/06/88: Welded on 4" dry hole marker - Dug up deadmen.
Well is Plugged and Abandoned.

Post 10-2
12-9-88
RHA

18. I hereby certify that the foregoing is true and correct

SIGNED

Ray A. Johnson

TITLE Production Accountant

DATE November 9, 1988

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

11-29-88

CONDITIONS OF APPROVAL, IF ANY:

Approved for plug back of the well bore,
10/05/88, and related until
surface location is completed.

*See Instructions on Reverse Side