NO. OF COPIES RECEIVED	RECE! ED	Form C-103
DISTRIBUTION	1 HELL.	Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE	NEW MEXICO OIL CONSERVATION COMMISSION 7	Effective 1-1-65
U.S.G.S.	49.	to the management of the second
LAND OFFICE	1	5a. Indicate Type of Lease
	0, 0, 0,	State X Fee.
OPERATOR '	ARTESIA, OFFICE	5. State Oil & Gas Lease No.
		K-4334
SUNDR	RY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PRO- USE "APPLICAT	OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FION FOR PERMIT -'' (FORM C-101) FOR SUCH PROPOSALS.)	
1.		7. Unit Agreement Name
WELL GAS X	OTHER-	
2. Name of Operator		8. Farm or Lease Name
Atlantic Richfield Com	npany 🦿	State BR
3, Address of Operator		9. Well No.
P. O. Box 1710, Hobbs,	New Mexico 88240	_
4. Location of Well	, Hew Mexico Gozzo	1
		LD. Field and Pool, or Wildcat Undesignated
UNIT LETTER K 19	980 FEET FROM THE SOUTH LINE AND 1980 FEET FROM	Undesignated
THE West LINE, SECTION	ON 16 TOWNSHIP 21S RANGE 26E NMPM	
	RANGERMPM	
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	3285.4 GR	///////
16.		Eddy
Check A	Appropriate Box To Indicate Nature of Notice, Report or Ot	ther Data
NOTICE OF IN	NTENTION TO: SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB X ST	PLUG AND ABANDONMENT
		irrace
	OTHER	
OTHER		
OTHER		
17. Describe Proposed or Completed Op	verations (Clearly state all pertinent details, and give pertinent dates, including	y estimated date of coating one
	perations (Clearly state all pertinent details, and give pertinent dates, including	gestimated date of starting any proposed
17. Describe Proposed or Completed Opwork) SEE RULE 1103.		
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30	$0/74$. Drilled $17\frac{1}{2}$ " hole to 516'. Ran 13 jts of	f 13-3/8" OD 48# &
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30	$0/74$. Drilled $17\frac{1}{2}$ " hole to 516'. Ran 13 jts of	f 13-3/8" OD 48# &
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510	$0/74$. Drilled $17\frac{1}{2}$ " hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, $\frac{1}{4}$ #	f 13-3/8" OD 48# & # Flocele slurry 12.7#.
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx C1 C 2% CaC1, \frac{1}{4}	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	$0/74$. Drilled $17\frac{1}{2}$ " hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, $\frac{1}{4}$ #	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx C1 C 2% CaC1, \frac{1}{4}	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs 30 mins OK.	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74. sg w/8 yds Readi-Mix to surface. WOC 24 hrs. T	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs 30 mins OK.	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs 30 mins OK.	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74. sg w/8 yds Readi-Mix to surface. WOC 24 hrs. T	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs 30 mins OK.	o/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CnCl, 5# Gilsonite, ¼# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74. sg w/8 yds Readi-Mix to surface. WOC 24 hrs. To see the surface work with the surface work and see the see to see the best of my knowledge and belief.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate. Tested csg to 1000# for
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs 30 mins OK.	0/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CaCl, 5# Gilsonite, 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74. sg w/8 yds Readi-Mix to surface. WOC 24 hrs. T	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs 30 mins OK.	o/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CnCl, 5# Gilsonite, ¼# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74. sg w/8 yds Readi-Mix to surface. WOC 24 hrs. To see the surface work with the surface work and see the see to see the best of my knowledge and belief.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate. Tested csg to 1000# for
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx C1 C 2% CaCl, ½ Cmtd behind 13-3/8" cs 30 mins OK.	D/74. Drilled 17½" hole to 516'. Ran 13 jts of 0' & cmtd w/300 sx HLW 2% CoCl, 5# Gilsonite, 4# Flocele slurry 14.8#. JC @ 12:15 PM 7/2/74. Sg w/8 yds Readi-Mix to surface. WOC 24 hrs. To above is true and complete to the best of my knowledge and belief. TITLE Dist. Drlg. Supv.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate. Tested csg to 1000# for
17. Describe Proposed or Completed Opwork) SEE RULE 1103. Spudded @ 1:45 PM 6/30 54# H-40 csg set @ 510 200 sx Cl C 2% CaCl, \frac{1}{4} Cmtd behind 13-3/8" cs 30 mins OK.	above is true and complete to the best of my knowledge and belief. TITLE Dist. Drlg. Supv.	f 13-3/8" OD 48# & # Flocele slurry 12.7#, Cmt did not circulate. Tested csg to 1000# for