

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-0560291

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal 00

9. WELL NO.

10. FIELD AND POOL OR WILDCAT

Undesignated (Morrow)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 18, T-21-S, R-27-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3208 GR

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

(PAGE 2)

FEDERAL "00" #2 (Continued from page 1)

2/6 WOC 3 hrs, ran 1", tag top of cmt @ 1373, pull 1" to 1303, Howco cmtd thru 1" w/ 250x Class C Neat cmt, POH, job compl @ 5 pm 2/5/75, WOC 7 hrs, ran 1", tag top cmt @ 1213, Howco cmtd w/ 50x Class C cmt w 2% CaCl, job compl @ 12:45 am 2/6/75, POH, WOC 6 hrs, prep to tag top of cmt.

FEDERAL "00" #2

2/7 (28) ND cmt 8-5/8 csq, correction on 20/6/75 rpt: tagged top of cmt @ 930, not 1213 as rptd, tag top of next plug @ 754, pull 1" to 744, Howco cmtd w/ 350x Class C cmt, job compl @ 8:30 am 2/6/75, WOC 6 hrs, tag cmt @ 870, pull 1" to 808, Howco cmtd w/ 50x Class C cmt w/ 4% CaCl, job compl @ 3 pm 2/6/75, WOC 3 hrs, tag top of cmt @ 870, pull 1" to 808, Howco spotted 50x Class C cmt w/ 4% CaCl, job compl @ 7 pm 2/6/75, WOC 3 hrs, tag top of cmt @ 749, pull 1" to 722, Howco cmtd w/ 50x Class C cmt w/ 4% CaCl, job compl @ 10:15 pm 2/6/75, WOC 3 hrs, tag top of cmt @ 749, pull 1" to 677, cmtd w/ 50x Class C cmt w/ 4% CaCl, job compl @ 6:15 pm 2/7/75, WOC 18 hrs. CONTINUED ON PAGE 3. CD 1259A, OK.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Authorized Agent

DATE 2/4/75

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE : 1965 O-685229

607-851

RECEIVED  
FEB 11 1972  
U.S. GOVERNMENT PRINTING OFFICE  
WASHINGTON, D.C.