FEDERAL "00" #2

(7) 1095 drlg lm, ll"\_hole, 1/17 3<sup>1</sup><sub>2</sub> @ 952, 3<sup>1</sup><sub>4</sub> @ 993, 3<sup>°</sup> @ 1055.

FEDERAL "00" #2

- (8) 1392 drlg anhy & lm, ll" hole, Fr Wtr w/o circ lost 100% circ @ 1173; 3° @ 1110; 2½ @ 1230; 3° @ 1365. Fr Wtr w/o circ 1/18
- Fr Wtr w/o circ. (9) 1685 drlg lm, ll" hole, 1/19 31/2 @ 1527, 41/2 @ 1647.
- (10) 1959 ND anhy & lm, ll" hole, Fr Wtr w/o circ. 1/20 44 @ 1709, 3-3/4 @ 1896, POH, mixing up pit of mud, will attempt to clean hole.

**FEDERAL "00" #2** 

(11) 1959 ND anhy & lm, 11" hole, Fr Wtr. 1/21Pmpd in pit of mud w/ bit @ 1959, attempted to drill, bit sticking, POH, ran DP OE to 1959, Howco spotted 100x Class C cmt w/ 2% CaCl on bottom @ 1959, job compl @ 2 pm 1/20/75, POH, WOC 4 hrs, ran bit, wash to bottom, no cmt plug, POH, rerun DP OE to 1959, Howco spotted 100x Class C cmt w/ 2% CaCl @ 1959, job compl @ 11:15 pm 1/20/75, POH, WOC 4 hrs, ran bit, had 5' of cmt plug 1939-1944, attempted to drill, bit sticking, pull bit to 1880, now mixing pit of mud.

FEDERAL "00" #2

(12) 19950 ND lm, ll" hole, NND dry drlg. finish mixing 1/22 pit of mud w/100 VIS CO hole to 1959'. Mix additional pit of mud. Drld from 1959-1990' POH. Ran DP OE wash to bottom. Howco spotted 200 sx Class C cmt w/2% CaCl & .05% CFR-2 on bottom POH WOC 6 hrs, ran bit tag top of cement @ 1940'. drilled cmt to 1980', stuck bit, worked loose in 1 hr. Pull bit to 1900', now mixing pit of mud.

**FEDERAL "00" #2** 

w/o circ. (13) 2116 drlg lm, ll" hole, 1/23 finish mixing pit of mud, drill from 1990-2022, mix pit of mud, drld from 2022-2053, mix pit & mud, drill from 2053-2084, mix pit of mud, drill from 2084-2116, now mixing pit of mud.

FEDERAL "00" #2

(14) 2271 drlg anhy & 1m, 11" hole, 3¼ @ 2140, dry drlg. 1/24mix pit of mud, drill from 2119-2147; mix pit of mud, drill from 2147-2202; mix pit of mud, drill from 2202-2271; now mixing mud.

FEDERAL "00" #2

- (15) 2398 ND anhy, 11" hole, 3-3/4 @ 2330, 8.5-75-NC. 1/25 drill from 2271-78 w/ mud & 2278-2398 w/ wtr,stuck bit, DC's & DP, worked loose & POH in 6-3/4 hrs, ran bit & CO to 2209, now mixing mud.
- (16) 2398 ND anhy, 11" hole, NND, 8.7-100-NC. 1/26 mixed 5 pits of mud, CO boulders from 2209-2356 past 24 hrs, cont to CO.

2

Fr Wtr.