Sacks Cement	Depth
50	10,275-10,125
50	9,125- 8,975
50	7,800- 7,650
35	5,600- 5,500
35	3,730- 3,630
35	2,010- 1,910
10	0- 20
10	•

Hole between cement plugs was filled with better than 25% gel; Dry hole marker set at surface with location marked thereon. Job complete 4:00 PM 4/6/75; No casing was pulled.

	$L_{i}^{\sigma}$ .	10	7. 7. <b>7.</b>	
8. I hereby cody that the forgoing of true incorrect SIGNED TITLE Regional Production	Mgr.	DATE	/25/75	
(This space for Federal or State office use)				
APPROVED BY TITLE TITLE CONDITIONS OF APPROVAL, IF ANY:  APPROVED SUBJECT TO POSSIBLE ADDITIONAL APPROVED SUBJECT TO PAD AND OR ROAD	<u> </u>	DATE		
CONDITIONS OF APPROVAL, IF ANY:  APPROVED SUBJECT TO POSSIBLE ADDITIONS  APPROVED ADDITIONS  APPROVED SUBJECT TO POSSIBLE ADDITIONS  APPROVED ADDI				

\*See Instructions on Reverse Side