(May 1963) SL (Do not use t	INDRY NC	TMLINF OF THE GEOLOGICAL SUP DTICES AND REP POSAIS to defile of to deeper ICATION FOR PERMIT	INTERIO RVEY ORTS ON	N WELLS	on re-	EDTOL STORES Budget Burea 5. LEASE DESIGNATION IC 050797 6. IF INDIAN, ALLOTTEE	u No. 42-R1424. AND BERIAL NO.
I. GAS WGUL WEI		CATION FOR FERMIT-		ECEIVE		7. UNIT AGREEMENT NA.	ME
2. NAME OF OPERATOR Cities Service Oil Company				111 3 1075		8. FARM OR LEASE NAM Government A	
3. ADDRESS OF OPERATOR Box 1919 - Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements).					9. WELL NO. 2 10. FIELD AND POOL, OR WILDCAT		
Soe also space 17 At surface	below.)	of Sec. 13-T20S-		ARTESIA, OFFICE		Undes. Alarte 11. SEC., T., R., M., OR B SUEVEY OR ABEA Sec. 13-T2OS	LK. AND
14. PERMIT NO.		15. ELEVATIONS (Show 3255' GR		-		12. COUNTY OR PARISH Eddy	
16.	Check A	Appropriate Box To li	ndicate Nati	ure of Notice, Repo		ther Data ENT REPORT OF :	
TEST WATER SHU FRACTURE TREAT SHOOT OR ACIDIZJ REPAIR WELL (Other)	T-OFF	FULL OR ALTER CASING Multiple complete Abandon® Change plans		WATER SHUT-OFF FRACTURE TREATME SHOOTING OR ACID: (Other) Set & (Note: Repor Completion of	cement	REPAIRING W ALTERING CA ABANDONMEN ing 5-1/2" csg of multiple completion of tion Report and Log for	sing T [•] • X Dn Well

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •

T.D. 11,610' Lime, Shale and Sand. PBTD 11,421' Lime and Shale. Waiting on completion unit. This well was drilled to a T.D. of 11,610' to test the Morrow formation. Displaced a 50 sack Class H w/0.5% CFR-2 cement plug @ 11,521' - 11,421' across top of Chester. Plug down @ 6:10 PM on 6-24-75. Displaced a 165 sack Class H w/3# salt/sack and 0.5% CFR-2 cement plug @ 10,968' - 10,685' across top of Morrow and extending into Atoka for a PBTD of 10,685'. Plug down @ 7:45 PM on 6-24-75. WOC 12 hrs. Tagged top of cement plug @ 10,692! (corrected PBTD). Set 22,000# on cement plug - Held O.K. Attempted to run a DST in the Atoka @ 10,586! - 10,692! and the cement plug failed after 1 min. and tools dropped 30'. Pulled test tools. Tagged top of soft cement @ 10,692'. Washed down to 10,719'. Drilled hard cement @ 10,719' - 10,734'. Set down w/30,000# with pump kicked in. Did not wash out. Set down w/55,000# with pump shut off - Held O.K. Ran a DST in the Atoka Sand. Drilled cement plug @ 10,734' - 11,010' and bit fell free. Ran bit to 11,421' and conditioned hole. Ran 25 Jts. (1051.49') 5-1/2" OD 20# N-80 and 224-1/2 Jts. (10315.48:) 5-1/2" OD 17# N-80 casing set and cemented @ 11,380' w/1000 sacks Class H w/0.6% CFR-2 and 5# KCl/sack cement. Plug down @ 5:15 PM on 6-29-75. Bumped plug with 2700# - Held O.K. WOC 7 hrs. Ran Temp. Survey. Top of cement @ 7420'.

18. I hereby certify that the foregoing is frue and correct SIGNED	TITLE Region Operation Manager	DATE July 1, 1975
(This space for Federal or State office use)	· ·	
APPROVED-BY CONDECTONS OF APPROVAL, IF ANY:	TICLE	DATE
ADDRU	see Instructions on Reverse Side	