

0157

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

DEC 08 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Kaiser-Francis Oil Company

3. Address and Telephone No.  
P. O. Box 21468, Tulsa, OK 74121-1468 918-491-4314

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
SW SE (660' FSL & 1980' FEL ) of Sec. 8-21S-26E

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.  
NM-0491036

6. If Indian, Allottee or Tribe Name  
-

7. If Unit or CA, Agreement Designation  
NM-85348

8. Well Name and No.  
A. M. Federal #1

9. API Well No.  
30-015-21521

10. Field and Pool, or Exploratory Area  
Soapberry Draw (Delaware)

11. County or Parish, State  
Eddy, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

The above well was P & A'd as follows:

1. Killed well w/10# brine. TOOH w/tbg. and packer.
2. Set cmt retainer @ 4020'. Pumped 35 sxs cmt through retainer & dumped 2 sxs cmt on top.
3. Circ'd hole w/10# brine.
4. Cut off @ 3000' and pulled 5 1/2" casing OOH.
5. Set 60 sx cmt plug 50' in and out of cut off casing. (3050'-2950') Tagged @ 2888'.
6. Set 50 sx cmt plug from 2060' - 1941'. Tagged at 1941'.
7. Set 50 sx cmt plug from 550' - 425'.
8. Set 20 sx cmt plug from 63' to surface.
9. Cut off surface casing and installed dryhole marker.

Operations began: 11/1/93  
Operations complete: 11/2/93

BLM witness on location: Kathy Queen

Approved by: [Signature]  
Title: [Signature]

NOV 15 8 32 AM '93

RECEIVED

14. I hereby certify that the foregoing is true and correct

Signed C. Jan Valkenburg Title Charlotte Van Valkenburg Date 11/10/93  
(This space for Federal or State office use)  
Approved by (ORIG. SGD.) DAVID R. GLASS Title Petroleum Engineer Date DEC 01 1993  
Conditions of approval, if any: