NO. OF COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103
FILE		Effective 1-1-65
U.S.G.S.	RECEIVED	Sq. Indicate Type of Leasa
LAND FICE		State X Fee
OPEF OR		5. State Oil & Gas Lease No.
	SEP 2 5 1975	к-6364
SUN	DRY NOTICES AND REPORTS ON WELLS	mmm, mmmm
(DO NOT USE THIS FORM FOR USE **APPL	ICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	$\chi_{111111111111111111111111111111111111$
	ARTESIA, OFFICE	7. Unit Agreement Name
WELL WELL	OTHER. Dry Hole	
2. The of Operator	8. Farm or Lease Name	
Cities Service Oil	State CS	
3. Address of Operator	9. Well No.	
Box 1919 - Midland,	נ 🔰 🕹	
4. Location of Well	10, Field and Pool, or Wildcat	
UNIT LETTER	1980 FEET FROM THE South LINE AND 660 FEET FROM	Und. Burton Flat Mor.
THE West LINE, SE	CCTION 17 TOWNSHIP 21S BANGE 27E NMPM.	AIIIIIIIIIIIIIIIIIIIIII
	15. Elevation (Show whether DF, RT, GR, etc.)	
	12. County	
	3233' DF	Eddy
^{16.} Chec	ek Appropriate Box To Indicate Nature of Notice, Report or Oth	er Data
NOTICE OF	FINTENTION TO: SUBSEQUENT	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
~	OTHER Well completion	data X
OTHER		
 Describe Proposed or Completed work) SEE RULE 1103. 	d Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of the ong any proposed

T.D. 11,557' Sand & Shale. PBTD 11,255'. Prep to plug and abandon.

Drilled and cleaned out to 11,514' and circulated hole with fresh water w/2% KCL added. Spotted 80 gals 10% acetic acid w/additives @ 11,463 - 11,377'. Perforated the Morrow Zone w/2-0.40" holes each @ 11,450', 11,451', 11,455', 11,461', 11,462' and 11,463'. Ran and set 2-7/8" OD tubing and a Baker A2 Lok-Set packer @ 11,344'. Swabbed part of load with gas TSTM. Acidized the Morrow zone thru perfs 11,450 - 11,463' w/1500 gals 7-1/2% MS acid w/additives + 1000 SCF/ bbl Nitrogen + 18 ball sealers. Well balled out. Max. press. 7200#, min. press. 4700#, AIR 4.3 B/M, ISIP 4700#, 15 min SIP 3500#. Flowed 61 BFW with gas @ rate of 200 MCFD/8 hrs thru 1" choke, FTP 20#. Swabbed 24 BFW/3 hrs with gas TSTM. Pulled tubing and packer set @ 11,344'. Ran tubing with a RTTS tool set @ 11,255' and squeezed Morrow perfs 11,450 - 11,463' with 75 sacks Class H w/6# KCl and 0.8% Halad 22 followed by 50 sacks Class H w/0.3% HRL cement. Max. press. 4200# (walking squeeze) w/45 sacks in formation, 20 sacks in 5-1/2" casing below RTTS, reversed out 60 sacks. Pressured tested to 4200# - Held O.K. Pulled tubing and RTTS tool. Drilled and cleaned out to 11,490' and spotted 100 gals 10% acetic acid @ 11,490 - 11,390'. Perforated the Morrow zone w/10-0.40" holes@ 11,460 - 11,465'. Ran and set 2-7/8" OD tubing and a Baker Lok-Set A-2 packer @ 11,379'. Swabbed dry with gas TSTM. Acidized the Morrow zone thru perfs 11,460 - 11,465' w/1500 gals 7-1/2% MS acid w/additives + 14 ball sealers and 1000 SCF Nitrogen/bbl. Press. annulus to 1100# - Held O.K. Max. press. 6800#, min. press. 5200#, ISIP 4000#, AIR 4.6 B/M, 5 min SIP 3300#, 10 min SIP 3000#, 20 min SIP 2700#. 12 hr 18. I hereby certify that the information above is true and complete to the best of dy incovering and belief.

SIGNED	Efuilden	TITLE Region Operation Manager	·
AFPROVED BY	a. Sieset	TITLESUPERVISOR, DISTRICT_II	SEP 25 1975

CONDITIONS OF APPROVAL, IF ANY: