

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Santa Fe	
BLM	
Land Office	
B of M	
Operator	

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21577
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2394
7. Lease Name or Unit Agreement Name Allied Comm
8. Well No. 2
9. Pool name or Wildcat Penlon Delaware

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED
2. Name of Operator Manzano Oil Corporation 505/623-1996	
3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107	
4. Well Location Unit Letter B : 767' Feet From The North Line and 1830 Feet From The East Line Section 27 Township 20S Range 27E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, CR, etc.) 3259' GL	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/11/89 Received verbal approval to plug & abandon well from Mike Williams.
7/18/89 POH with 2" tubing. Pull & lay down 34 jts. 4-1/2" casing & 3-1/2" x 7-5/8" casing guide. TIH with tubing to 1234'. Pump 25 sacks Class C & 4% CaCl. Wait 1 hr, tag cement @ 1085' - 145' of fill. Pull to 1044'. Load hole with 10# per gal fluid. Pump 35 sacks Class C & 4% CaCl. Wait 1 hr, tag no fill. Pump 40 sacks Class C & 4% CaCl. Wait 1-1/2 hr, tag @ 1019' - 25' of fill. Pump 20 sacks Class C & 4% CaCl. Pull to 600' & SI for night.
7/19/89 Tag @ 944' - 75' of fill, 100' total fill. POH, set 60' surface plug with 20 sacks Class C cement. Cut off 8-5/8" surface casing. Welded dry hole marker.

Post ID-2
8-11-89
P4A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Alfreda Uddeggen TITLE Drilling Secretary DATE August 3, 1989

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

APPROVED BY Darrell Moore TITLE Geologist DATE 10/31/89

CONDITIONS OF APPROVAL, IF ANY: