

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	2 v
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

NEW MEXICO OIL CONSERVATION COMMISSION

OCT 28 1976

O. C. C.

ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5115

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation ✓	8. Farm or Lease Name Stonewall EP State
3. Address of Operator 207 South 4th Street - Artesia, NM 88210	9. Well No. 1
4. Location of Well UNIT LETTER F 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 20S RANGE 28E NMPM.	10. Field and Pool, or Tract Burton Flats Wolf
15. Elevation (Show whether DF, RT, GR, etc.) 3282' GR - 3300' KB	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER Temp. Abandon Wolfcamp-Open Morrow <input checked="" type="checkbox"/>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-26-76 - TD 11478'; PBTD 11380'. Loaded Wolfcamp formation w/KCL water, unseated packer at 8836', retrieved bridge plug at 9024' and POCH. RIH w/tubing, sliding sleeve, blast joint and dual packer, landed tubing in on-off tool at 11146', set upper (dual) packer at 8817'. Prep to swab Wolfcamp.

10-27-76 - Swabbed Wolfcamp in, removed Blanking Plug from Morrow packer and set straight thru choke and Guiberson AA packer at 8817'. Completing the Morrow in the tubing. Wolfcamp blanked-off between packers.

Diagrammatic Sketch of Completion Attached.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Tomlinson TITLE Geol. Secty DATE 10-28-76

APPROVED BY W.A. Gussert TITLE SUPERVISOR, DISTRICT II DATE NOV 4 1976

CONDITIONS OF APPROVAL, IF ANY: