

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRI
(Other instruction
verse side)Copy 65 F
Form approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Dry & Abandoned		5. LEASE DESIGNATION AND SERIAL NO. NM-25487	
2. NAME OF OPERATOR Morris R. Antweil✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----	
3. ADDRESS OF OPERATOR Box 2010, Hobbs, New Mexico 88240		7. UNIT AGREEMENT NAME -----	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 1980' FWL Sec. 4-T21S-R26E		8. FARM OR LEASE NAME Roc Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3202' GR		10. FIELD AND POOL, OR WILDCAT Avalon 7, e 2000	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 4-T21S-R26E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NewMex.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 10,950' Plugged and Abandoned as follows:

- (1.) 50 sx. plug 10,460' - 10,610' across top of Morrow.
- (2.) 50 sx. plug 9,500' - 9,650' across top of Strawn.
- (3.) 50 sx. plug 8,050' - 8,200' across top of Wolfcamp.
- (4.) 50 sx. plug 6400' - 6,550' across top Second Bong Spring.
- (5.) 35 sx. plug 4,500' - 4,600.'
- (6.) 35 sx. plug 2,520' - 2,620' across 8-5/8" casing shoe.
- (7.) 10 sx. surface plug W/marker.

Well P & A 20 August 75.

RECEIVED RECEIVED
SEP 17 1975
OCT 21 1975
U.S. GEOLOGICAL SURVEY
NEW MEXICO
O.C.C.
ARTESIAN OFFICE

18. I hereby certify that the foregoing is true and correct

SIGNED

R. M. Williams

TITLE

Agent

DATE

12 Sept. 75

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

ADDITIONAL
OCT 24 1975
R. L. BLEKSLER
ACTING DISTRICT ENGINEERRoc Fed
LP 2
10-25-75