NO. OF COPIES RECEIVE	4,						
	ه ع					Form C-103	
DISTRIBUTION						Supersedes Old	
SANTA FE		NEV	MEXICO OIL CON	SERVATION COMMISSION		C-102 and C-10. Effective 1-1-65	
FILE	/	1		RECEI	/FD		
U.S.G.S.				7 2 0 2 1	. – –	5a. Indicate Type o	f Lease
LAND OFFICE						State	Fee X
OPERATOR	/	J		NOV 20 1	9/5	5. State Oil & Gas	Lease No.
(DO NOT USE THE	SUNDR	Y NOTICES A	AND REPORTS ON	WELLS BACK TO A DIFFER TO RELEVO	3.		
•	USE "APPLICAT	ION FOR PERMIT -	" (FORM C-101) FOR SU	CH PROPOSALS RTESIA, OF			
Name of Operator	SAS WELL	OTHER-	Dry Hole			7. Unit Agreement 1	
Hanagan Petroleum Corporation 🛩						8. Farm or Lease N Lowenbruck	ame
P. O. Box	1737	Roswe	ll, New Mexico	88201		9. Well No.	
. Location of Well	· · · · · · · · · · · · · · · · · · ·						or Wildcat
UNIT LETTER B		1980 FEET P	FROM THE East	LINE AND 660	FEET FROM	Burton Flat	t 77 : : : : : : : : : : : : : : : : : :
THE North	LINE, SECTIO	24	TOWNSHIP 215	RANGE	нмрм.		
			evation (Show whether 3184 GR - 32	·		12. County Eddy	
6.	Check /			Nature of Notice, Repo			77777777
NO	TICE OF IN	TENTION TO	:			REPORT OF:	
PERFORM REMEDIAL WORK		P	PLUG AND ABANDON	REMEDIAL WORK	<u></u>		-
EMPORARILY ABANDON	T T		TOO MILE REALIBOR			ALTERING	CASING
				COMMENCE DRILLING ODNO	1 1		19
ULL OR ALTER CASING		c	HANGE PLANS	COMMENCE DRILLING OPNS.		PLUG AND	ABANDONMENT X
PULL OR ALTER CASING		c	HANGE PLANS	CASING TEST AND CEMENT JO	в	PLUG AND	A BANDONMENT X
OTHER		c	HANGE PLANS	1	в	PLUG AND	ABANDONMENT X
	Completed Ope			CASING TEST AND CEMENT JO			
OTHER	Completed Op			CASING TEST AND CEMENT JO			
OTHER	Plugged a 9900-10,0	erations (Clearly and abandon 200; 8525-8	state all pertinent det ned as follows 3625; 6750-685	CASING TEST AND CEMENT JO	, including es	stimated date of star SX. plugs:	10,900-11,
Casing 16"-1- 178'-3	Plugged a 9900-10,0 @ 2510').	and abandon 8525-8 10 sx. s hole i''	state all pertinent det ned as follows 3625; 6750-685 surface plug w	other ails, and give pertinent dates (T.D. 11,393' 0: 4950-5050: 246	, including es	stimated date of star SX. plugs:	10,900-11,
Casing 16"-1- 178'-3	Plugged a 9900-10,0 @ 2510').	and abandon 8525-8 10 sx. s hole i''	state all pertinent det ned as follows 3625; 6750-685 surface plug w	casing test and cement Joother ails, and give pertinent dates : (T.D. 11,393' 0; 4950-5050; 246' /dry hole marker	, including es	stimated date of star SX. plugs:	10,900-11, 7-7/8" cs pulled.

CONDITIONS OF APPROVAL, IF ANY: