

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OIL CONS COMMISSION
Drawer DD
Artesia, NM 88210
FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Harvey E. Yates Company

3. Address and Telephone No.

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

G, 1980' FN & EL
SW/NE SEC. 31, T-20S, R-29E

5. Lease Designation and Serial No.

NM-19672

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

FANNIE LOU FEDERAL #1

9. API Well No.

30-015-21617

10. Field and Pool, or Exploratory Area

SCANLON MORROW

11. County or Parish, State

EDDY CO., NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☒ Casing Repair
☐ Altering Casing
☐ Other

CASING LEAK FIXED & TESTED
& TEST STRAWN & UPPER PAY

☐ Change in Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 5-25-95 SET PKR @ 6230'. TEST CASING BELOW PKR TO 1000# FOR 15 MIN. HELD OK. PULL PKR TO 6170' & SET. TEST CASING ABOVE PKR TO 500# FOR 15 MIN. HELD OK. PUMP DOWN TBG AND BROKE CIRC BETWEEN 4 1/2" AND 9 5/8" CASING. PULL OUT OF HOLE. PERF 4 SQZ HOLES @ 6250' (HOLE @ 6201'). SET HOWCO RETAINER @ 6100'.
- 5-26-95 CMT 4 1/2" ANNULUS w/ 300 SKS HOWCO LITE & 650 SKS CL "H" w/ .5% HALAD 9 AND 2.5#/GAL SALT.
- 5-31 & 6-1-95 DRILL OUT CMT RETAINER AND CEMENT. TEST CASING TO 500# FOR 15 MIN. HELD OK.
- 6-2-95 RAN CBL. TOC @ 3350'. 6-3-95 PERF STRAWN 10410-10453 (OA). 6-6-95 ACIDIZE w/ 3000 GALS 15% SRA. SWAB TO TEST.
- 6-8-95 SET CIBP @ 10375' + 50' CMT. ALSO SET CIBP @ 9194' (TOP OF WOLFCAMP) PLUS 50' CEMENT.
- 6-9-95 PERF DELAWARE 5671-5690.5' (OA). ACIDIZE w/ 2000 GALS 15% SRA. SWAB TO TEST.
- WELL SWABBED. CUTTING SLIGHT SHOW OF OIL. SI PENDING EVALUATION.
- 6-15-95 HOLE CIRC. w/ OXYGEN SCAVENGER & CORROSION INHIBITOR TO PROTECT CASING & TBG. REQUEST APPROVAL FOR FENCED PIT ON LOCATION NORTH OF WELL HEAD TO BE USED FOR ADDITIONAL OPERATION OR PLUGGING.

14. I hereby certify that the foregoing is true and correct

Signed RAY F. NOKES Title PROD. MGR./ ENG.

Date 6/26/95

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any: